PANDUIT[®] infrastructure for a connected world

Product Change Notification

PCN#: ID, SAFETY AND ACCESSORIES - 2017-12-15 Issue Date:

Impacted Regions: NA EMEA LATAM AP

Reason for Change: Discontinuation Other Material Change

DESCRIPTION OF CHANGE: Change from PVDF material to PVF material

Obsolution of the PVDF self-laminating labels and the replacement PVF self-laminating labels. The new GMT1 material has a higher tensile strength than the older PVDF material. The higher tensile strength provides greater resistance to the label tearing.

PHOTOS/DRAWING (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT (where applicable) PART NUMBERS: Reference page 2/linked PDF

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:				
Schedule for Change	Year (YYYY)	Month (MM)	Day (DD)	
New product sample availability date	2018	02	31	
Old product discontinuation date*	2018	12	30	

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.

PANDUIT[®] infrastructure for a connected world

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)	
S050X150T1T	S050X150TAT-A	
S075X125T1T	S075X125TAT-A	
S100X075T1T	S100X075TAT-A	
S100X125T1T	S100X125TAT-A	
S100X150T1T	S100X150TAT-A	
S100X225T1T	S100X225TAT-A	
S100X400T1T	S100X400TAT-A	
S200X400T1T	S200X400TAT-A	
S100X150T1J	S100X150TAJ-A	
S100X225T1J	S100X225TAJ-A	
S050X075T1D	S050X075TAD-A	
S050X150T1D	S050X150TAD-A	
S075X150T1D	S075X150TAD-A	
S100X075T1D	S100X075TAD-A	
S100X138T1D	S100X138TAD-A	
S100X150T1D	S100X150TAD-A	
S100X244T1D	S100X244TAD-A	
S100X387T1D	S100X387TAD-A	
S100X650T1D	S100X650TAD-A	
S200X150T1D	S200X150TAD-A	
S200X400T1D	S200X400TAD-A	

