

PF	ODUCT CHAN	GE NOTIFICAT	ΓΙΟΝ	
Product Category		OUTLETS	2	20200807-1
Product Group		ROAR		
ISSUE DATE:			10-Aug-20	
IMPACTED REGIONS:	✓ NA ✓ EM	EA 🔽 LATA	AM☑ AP	
REASON FOR CHANGE:	✓ DISCONTINUATION✓ OTHER			
DESCRIPTION OF CHANGE: (Required)				
Angled versions of patch panel brackets 2RU brackets will no longer be available				
Angled version of patch panel brackets IMPACTED PART NUMBERS AND RE		(where applicable)	brackets	
Reference Page 2 / Linked PDF		Times application		

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2020	11	10

^{*}Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Replacement Type	Replacement Part 1
CPPBRKT/N	No Replacement	
CPPBRKT3/N	Direct Replacement	CPPTBRKT3/N
CPPBRKT4/N	Direct Replacement	CPPTBRKT4/N