

PRODUCT CHANGE NOTIFICATION

PCN#: RACKS CABLE MGMT

20190320

ISSUE DATE: _____ 20190401


IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

Product Change Notice of removal of End of Row Bracket from 45RU PatchRunner 2 Manager hardware kits. This will be a running change.

End of row bracket condition (7ft Vertical Cable Managers Only)



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
PR2VD06	
PR2VD08	
PR2VD10	
PR2VD12	
PR2VSD06	
PR2VSD08	
PR2VSD10	
PR2VSD12	
PR2VFD06	
PR2VFD08	
PR2VFD10	
PR2VFD12	
PR2V06	
PR2V08	
PR2V10	
PR2V12	
PR2VF06	
PR2VF08	
PR2VF10	
PR2VF12	
PR2VD06WH	
PR2VD08WH	
PR2VD10WH	
PR2VD12WH	
PR2VSD06WH	
PR2VSD08WH	
PR2VSD10WH	
PR2VSD12WH	
PR2VFD06WH	
PR2VFD08WH	
PR2VFD10WH	
PR2VFD12WH	
PR2V06WH	
PR2V08WH	
PR2V10WH	
PR2V12WH	
PR2VF06WH	
PR2VF08WH	
PR2VF10WH	
PR2VF12WH	