1 Products affected

Product hierarchy no. * Part no			archy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Туре				
02	006	019	0000001800	See list below	Power Entry Module with Filter	5003	
*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)							

List of a set as we affected

List of part number	rs affected			
5003.1111.1	5003.1311.1	5003.2111.1	5003.2311.1	
5003.1211.1	5003.1411.1	5003.2211.1	5003.2411.1	
5003.1121.1	5003.1221.1	5003.1321.1	5003.1323.1	5003.1421.1
5003.115B.1	5003.125B.1	5003.135B.1	5003.145B.1	
5003.116B.1	5003.126B.1	5003.136B.1	5003.146B.1	


2 Type of change

Filter cases for front and rear mounting have a new surface treatment process in order to product improvement.


3 Detailed description of change

Surface treatment process of filter case has changed with no change of surface material.

Screw versions front-side



Screw versions rear-mounting



5003						0118.2248	
creation date	created by	release date	released by	notification no.	revision	page	
2014-10-28	buechlpi	2015-01-22	buechlpi	26907	_	1 of 2	





4 Reason of change

Market request.

5 Release date

The change will be rolled-out starting ww 04/2015 and lasts approx. 12 months depending on the variant.

6 Impact of change and recommended action

Form:	No	No change to form but more shiny surface
Fit:	No	There are no dimensional changes
Function:	Yes	Improved resistance against corrosion
Production Site:	No	There is no change of the production site
Product Label:	No	No change to product label
Customer action	No	Notification only

7 Reference Documents / Attachments

Kind of document	Document number	Remarks		
Data sheet	5003	http://www.schurter.com/pdf/english/typ_5003.pdf		

5003						0118.2248	
creation date	created by	release date	released by	notification no.	revision	page	
2014-10-28	buechlpi	2015-01-22	buechlpi	26907	_	2 of 2	