

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU PG	PGU	Type				
02 006	016	0000001605	See list below	Power Entry Module with Filter	5150	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
5150.0011.0	5150.0021.0	5150.0031.0	5150.0041.0	
5150.0011.1	5150.0021.1	5150.0031.1	5150.0041.1	


2 Type of change

Filter cases for front and rear mounting have a new surface treatment process in order to product improvement.


3 Detailed description of change

Surface treatment process of filter case has changed with no change of surface material.

Screw versions front-side



Screw versions rear-mounting



5150					0118.2253	
creation date	created by	release date	released by	notification no.	revision	page
2014-12-17	buechlp	2015-01-20	buechlp	26907	-	1 of 2

4 Reason of change

Market request.

5 Release date

The change will be rolled-out starting ww 04/2015 and lasts approx. 12 months depending on the variant.

6 Impact of change and recommended action

Form:	No	No change to form but more shiny surface
Fit:	No	There are no dimensional changes
Function:	Yes	Improved resistance against corrosion
Production Site:	No	There is no change of the production site
Product Label:	No	No change to product label
Customer action	No	Notification only

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet	5150	http://www.schurter.com/pdf/english/typ_5150.pdf

5150					0118.2253	
creation date	created by	release date	released by	notification no.	revision	page
2014-12-17	buechpi	2015-01-20	buechpi	26907	-	2 of 2