

Date: March 2021

EOL Ref No: 0030

## Subject: Tango6A and Tango6B Antenna EOL End Of Life Notice

Details of replacement parts, where available, are specified below. The change method details where small volume stocks of discontinued parts remain in stock. Orders for discontinued parts will be switched to replacement parts and notified at time of order.

## **Product Affected:**

Part Number: <i>sap code</i>	Replacement:	Change Method
33485	None	Immediate
Full Part Number:	Full Part Number:	See Notes Page
TANGO6B/4M/SMAM/SMAM/SMAM/RP/S/S/20	None	Not applicable
Reason for change:	Manufacturing change	
Add detail description	Add images as necessary	
Part No Longer in Production		
Availability Date	Last Shipment Date	
See reference documentation below for additional notes and guidance		
File Name:	Description:	

Part Number: <i>sap code</i>	Replacement:	Change Method
33785	None	Immediate
Full Part Number:	Full Part Number:	See Notes Page
TANGO6A/4M/SMAM/SMAM/S/S/20	None	Not applicable
Reason for change:	Manufacturing change	
Add detail description	Add images as necessary	
Part No Longer in Production		
Availability Date	Last Shipment Date	
See reference documentation below for additional notes and guidance		
File Name:	Description:	

		1
Part Number: <i>sap code</i>	Replacement:	Change Method
34020	None	Immediate
Full Part Number:	Full Part Number:	See Notes Page
TANGO6A/3M/SMAM/SMAF/RP/S/20	None	Not applicable
Reason for change:	Manufacturing change	
Add detail description	Add images as necessary	
Part No Longer in Production		
Availability Date	Last Shipment Date	
See reference documentation below for additional notes and guidance		
File Name:	Description:	
	-	

Part Number: <i>sap code</i>	Replacement:	Change Method
60777	None	Immediate
Full Part Number:	Full Part Number:	See Notes Page
TANGO6A/3M/SMAM/SMAM/S/20	None	Not applicable
Reason for change:	Manufacturing change	
Add detail description	Add images as necessary	
Part No Longer in Production		
Availability Date	Last Shipment Date	
See reference documentation below for additional notes and guidance		
File Name:	Description:	

Part Number: <i>sap code</i>	Replacement:	Change Method
60788	None	Immediate
Full Part Number:	Full Part Number:	See Notes Page
TANGO6A/3M/SMAM/SMAM/RP/S/20	None	Not applicable
Reason for change:	Manufacturing change	
Add detail description	Add images as necessary	
Part No Longer in Production		
Availability Date	Last Shipment Date	
See reference documentation below for additional notes and guidance		
File Name:	Description:	