

TAIYO YUDEN

TAIYO YUEN (USA) INC.
2107 North First Street
Suite 450
San Jose, CA 95131
Tel: (800) 368-2496
Fax: 408-213-011

DISCONTINUATION NOTICE

DATE: February 25, 2015

RE: LEADED COMMON MODE CHOKE COILS FOR AC LINES

Part Number: TLF14CB □□□K1
TLF14CBH□□□K1

LAST ORDER
ACCEPTANCE: July 2, 2015. Taiyo Yuden will not accept order after this date.

REF NO.: UTY-DN15-03D

Taiyo Yuden (U.S.A.) Inc. hereby gives notice that the following part number will be discontinued. Orders will be accepted for these parts through July 2, 2015 for deliveries through August 14, 2015. Orders for these components received after the issue date of this notice are Non-Cancelable and Non-Returnable.

| TLF14CB | Note | TLF14CBH | Note |
|-----------------|----------------|------------------|----------------|
| TLF14CB1021R5K1 | No replacement | TLF14CBH1021R5K1 | No replacement |
| TLF14CB1030R7K1 | No replacement | TLF14CBH1030R7K1 | No replacement |
| TLF14CB1312R0K1 | No replacement | TLF14CBH1830R5K1 | No replacement |
| TLF14CB1830R5K1 | No replacement | TLF14CBH2221R2K1 | No replacement |
| TLF14CB2221R2K1 | No replacement | TLF14CBH2230R4K1 | No replacement |
| TLF14CB2230R4K1 | No replacement | TLF14CBH2721R1K1 | No replacement |
| TLF14CB2730R4K1 | No replacement | TLF14CBH3321R0K1 | No replacement |
| TLF14CB3321R0K1 | No replacement | TLF14CBH3330R3K1 | No replacement |
| TLF14CB3330R3K1 | No replacement | TLF14CBH4721R0K1 | No replacement |
| TLF14CB3921R0K1 | No replacement | TLF14CBH4730R2K1 | No replacement |
| TLF14CB3930R3K1 | No replacement | TLF14CBH5620R8K1 | No replacement |
| TLF14CB4721R0K1 | No replacement | TLF14CBH5630R2K1 | No replacement |
| TLF14CB4730R2K1 | No replacement | TLF14CBH6820R8K1 | No replacement |
| TLF14CB5620R8K1 | No replacement | TLF14CBH6830R2K1 | No replacement |
| TLF14CB5630R2K1 | No replacement | | |
| TLF14CB6012R0K1 | No replacement | | |
| TLF14CB6820R8K1 | No replacement | | |
| TLF14CB6830R2K1 | No replacement | | |
| TLF14CB8220R8K1 | No replacement | | |

NOTE: The information in this notice is applicable only to Taiyo Yuden customers in North and South America. Discontinuation schedules and availability may vary in other regions. To best serve you, all inquires and requests should be directed through the normal sales channels or you can contact the nearest Taiyo Yuden Sales Office.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department