March 11, 2022

Information Note New label for EMC filters from Szombathely

A new standardized label is being introduced for EPCOS EMC filters of the series B84142B*R000 (see pictures below). The marking on the terminals is going to be dropped. The changes apply only to EMC filters produced in Szombathely/Hungary. The EMC filters themselves remain unchanged.

Affected products

Ordering code	Туре
B84142B0008R000	Drive filters
B84142B0012R000	Drive filters
B84142B0016R000	Drive filters
B84142B0025R000	Drive filters

Scheduled date of introduction: June 20, 2022 Estimated date of first deliveries: June 20, 2022


EMC-Filters, Feedthrough Components Internal / External

220311EMC1e


March 11, 2022

Label change at B84142B0008R000

previous




new



March 11, 2022

Label change at B84142B0012R000

previous




new




March 11, 2022

Label change at B84142B0016R000

previous




new



March 11, 2022

Label change at B84142B0025R000

previous



March 11, 2022

Enclosure IN (ID No. MAG-744140222)

Contact Philipp Riedl, MAG PEMC PM, Munich

Customers are asked to address inquiries directly to their sales contacts.



Information Note

-

1.	1. ID No. MAG-744140222		2. Date of announcement March 11, 2022			
3.	Product / product group	Old ordering code	New ordering code	Customer part number		
	EMC Filter	B84142B0008R000	no change			
		B84142B0012R000				
		B84142B0016R000 B84142B0025R000				
		D04142D0023R000				
4.	Description of change					
	The label of the product series B84142B*R000 will be modified as shown in UPtoDATE.					
	Furthermore the marking on the terminals is going to be dropped.					
5.	Effect on the product or for the customer (benefit, quality, specification, lead time)					
	The former marking of B84142B0025R000 showed L1 respectively L1' on the terminals. This sometimes caused problems on customer side. Operators could connect the EMC filter to L1 because of the terminal marking, although it might have been intended to be connected to L3.					
	By dropping the terminal marking and adjusting the label, this misunderstanding cannot happen any more.					
	To be consistent, also the labeling of B84142B0008R000, B84142B0012R000 and B84142B0016R000 will be					
	modified accordingly.					
6.	Quality assurance measures / risk assessment					
	Not applicable.					
7.	Scheduled date of change June 20, 2022					
8.	Estimated date of first del	ivery of changed produ	ct June 20, 2022			
	For an interim period we cannot rule out that old as well as new products will be shipped.					
	Future shipments can consist of old and new products as the new changed product is used as an alternative to the old product.					
	Quality Management		Signature			
	Name Wolfgang Woitsch		Signed Woitsch			
	Product Marketing					
	Name Philipp Riedl		Signature			
	Tel. +49 89 54020 3520		Signed Riedl			
	Email philipp.riedl@tdk.co	m				