

TE Connectivity

Product Change Notification: P-20-019798 PCN Date: 16-OCT-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Hollow Shaft Resolvers, V23401 Family

Description of Changes

This product change notification is related to all TE size 21 resolvers with type T2 aluminium housing. In order to ensure component availability, there will be a second source of housing implemented in addition to the existing machined aluminium housing. The new components will be produced using die cast plus machining processes. There will be an added groove on the outer surface of the existing machined type T2 housing in order to differentiate between these two resolver housing sources in case of dual use. There is no change in resolver manufacturing process, product form, fit and any technical functions of the products. Please don't hesitate to contact your TE representative in case of any questions.

Other attachments:

Hollow Shaft (T2) Resolvers Descriptions

| Reason for Changes: | | | | | | |
|--|--|--|--|--|--|--|
| Product improvement. | | | | | | |
| Estimated Dates: | | | | | | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | | | | |
| | 15-DEC-2020 | | | | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | | | | |
| | No Mixed Shipments | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|------------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| <u>2350437-1</u> | NO | | | | | | |
| 2360964-1 | NO | | | | | | |
| <u>2367236-1</u> | NO | | | | | | |
| <u>2367237-1</u> | NO | | | | | | |
| 2367254-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 2350437-1 | NO | | | | | | |
| 2360964-1 | NO | | | | | | |
| 2367236-1 | NO | | | | | | |
| 2367237-1 | NO | | | | | | |
| 2367254-1 | NO | | | | | | |