

## **Product Change Notification**



Product Group: Vishay Dale/July 28, 2020/PCN-DI-00485-2020 Rev 0

## **Tolerance change on terminal for IHSM-5832**

**DESCRIPTION OF CHANGE:** The terminal width tolerance on the IHSM-5832 series is changing from  $0.217 \pm 0.005$  [5.51  $\pm 0.13$ ] to  $0.217 \pm 0.01$  [5.51  $\pm 0.254$ ].

**CLASSIFICATION OF CHANGE:** Assembly Process/Structure

**REASON FOR CHANGE:** This change it to correct the data sheet only. There will be no change to the part that we are currently manufacturing.

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: N/A

**PRODUCT CATAGORY: Inductors** 

PART NUMBERS/SERIES/FAMILIES AFFECTED: IHSM5832\*

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE:

Start Shipment Date: Immediately

Last Time Buy Date: NA Last Time Shipment Date: NA

**SAMPLE AVAILABILITY: N/A** 

PRODUCT IDENTIFICATION: N/A

**QUALIFICATION DATA:** Available upon request

This PCN is considered approved, without further notification, unless we receive specific customer concerns or as specified by contract.

**ISSUED BY:** Doug Lillie, Sr. Product Marketing Manager

For further information, please contact your regional Vishay office.

## **CONTACT INFORMATION:**

The Americas

Vishay Intertechnology, Inc 1505 East Highway 50 P. O. Box 180 Yankton, South Dakota 57078

Ph: 1 605-665-9301 Fax: 1 605-665-1627 doug.lillie@vishay.com **Europe** 

Vishay Electronic GmbH Dr.-Felix-Zandman-Platz 1 95100 Selb

Germany

Ph: 49-9287-71-2282 Fax: 49-9287-71-2496 jens.walther@vishay.com Asia

Vishay Asia Pte Ltd. 25 Tampines Street 92 Keppel Building #02-00 Singapore 528877 Ph: +65-788-6668 Fax: +65-788-3383 victor.goh@vishay.com