

Product / Process Change Notice

No.: Z200-PCN-TM201901-01-A

Date: January 22, 2019

Change Title : To add	I Powertech (PTI) as an additional fir	al test site for	1G/2G DRAM with	VFBGA96(7.5X13
DDR3 package.					

Change Classification: ☑ Major □ Minor with customer notification Change item : □ Design □ Raw Material □ Wafer FAB □ Assembly ☑ Testing □ Packing □ Others

Affected Product(s) :

Please refer to Table 1 in details.

Description of Change(s)

To add Powertech Technology Inc.(PTI) as an additional final test site for 1G/2G DRAM with VFBGA96(7.5X13) DDR3 package. (PTI address: No. 10, Datong Rd., Hsinchu Industrial Park, Hukou, Hsinchu, Taiwan.)

Reason for Change(s) :

To increase the production capacity and meet customer delivery requirement

Impact of Change(s) : (positive & negative)

Form : No Change

Fit: No Change

Function : No Change (Please refer to attachment I)

Reliability : No Concern (Please refer to attachment II)

Hazardous Substances: No Change

Qualification Plan/ Results :

(1) PTI is one company with ISO/IATF16949 and ISO 9001 certification.(Please refer to attachment III)

(2) Based on Winbond standard package qualification result, the new production line meets criteria.

Implementation Plan :

Date Code: _____ onward D Lot No: _____ onward

Proposed first ship date: <u>April 24, 2019</u>

Originator: (QA)	Ц	huang	Approval: (QA Dept. Manager)	4H Chang	Approval: (QRA Director)	Ceron
Contact for Ques & Concerns		Name: <u>Betty Huang</u> TEL: <u>886-3-5678168</u> (ext.76549) FAX: <u>886-3-5796124</u> Address : <u>No. 8,Keya 1st Rd., Daya Dist., Central Taiwan Science Park, Taichung</u> <u>City 42881,Taiwan</u> E-mail: <u>Hyhuang8@winbond.com</u>				



Customer Comments:

Note: Please sign this notice, and r Change Request will be assumed t		ct within 30 days. If no response is received wit	hin 30 days, this
Major change: D Approval	Disapproval	Conditional Approval :	
Minor change with customer n	otification: 🗖 Recognit	ion	
Comment:			
Date:			
Dept. name:			
Person in charge:			



Table 1. The affected part no are list below.

W632GG6MB-07	W632GG6MB-15	W632GU6MB-12	W631GG6MB-11	W631GU6MB-09
W632GG6MB-08	W632GU6MB-08	W632GU6MB-15	W631GG6MB-12	W631GU6MB-11
W632GG6MB-09	W632GU6MB-09	W631GG6MB-08	W631GG6MB-15	W631GU6MB-12
W632GG6MB-11	W632GU6MB-11	W631GG6MB-09	W631GU6MB-08	W631GU6MB-15
W632GG6MB-12				