

Doc. No. : PCN 130801 **Date :** 2013/08/05

To: Dear Valued Customers


Product Change Notice

Subject:

SOD-123H Devices Change for Overall Appearance

Parts Affected:

CGRMT4004-HF / CGRMT4007 series will be changed and produced by new mold. Changes of size are shown as below pictures:



Reason for Change:

- 1. Current molding design is strip-type mold. It tends to cause chipping on the edge of devices after singulation by multi-cutter technic.
- 2. Productivity and inspection becomes low and difficult according to our standard of chipping(<0.2mm).
- 3. Therefore, our supply cannot meet demand from customers.
- 4. Strip-type mold is replaced withmulti-cavity of strip type mold. To limit the range of chipping bythe

trenches which facilitates devices to conform with standard of chipping after cutting technic.

Effect of Change:

- 1. Change of overall molding will not affect the readability of marking.
- 2. Change of overall molding will not affect electricity characteristics and hermetic seal.

Effective Date of Change:

2014/1/25



Please complete the form below duly signed and fax back to Comchip Technology Co.

Please select your answer	Date
1. Approved this PCN	
2. Approved this PCN with conditions	Responsibility By
3. Disapproved this PCN	
Please specify the condition or explain the reason if you select 2 or 3.	

Comchip Technology Co., Ltd. TEL: +886-2-86776675 FAX: +886-2-86776672