

Product Change Notification

Date
June 30, 2022

Product

Connect IT 4/16/48/Mini

Description of change

New firmware version 22.5.50.62 available for Connect IT products. This is a major production release. Digi recommends all customers update their Connect IT products to firmware v22.5.50.62

Reason for Change

New Firmware Version 22.5.50.62 provides:

- New Features
- Enhancements
- Bug Fixes
- Security Fixes

See Release Notes for more details.

Product Notice

A new stable firmware version has been released for the Connect IT products, version 22.5.50.62. Use the link below to view the full list of changes, features, and fixes included in the new firmware.

Connect IT Release Notes

<u>To take advantage of the new features, you must take action to update</u> <u>your device.</u> Refer to the instructions to update your firmware in the release notes above for more information.

Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the <u>Digi Support team</u>

Affected Part Numbers

IT16-1002, IT48-1002, IT01-M100, ASB-5402-RM

Timing of Change

Effective Immediately