PRODUCT CHANGE NOTIFICATION E-Switch Series/ Part No affected N324000 thru N324011 Part /Series Description: TL3240 Affected Process X Assembly Stamping Molding **Plating** Change on: **Process** X Drawing Material Specification Packaging **Tooling Modification New Tooling** Manufacturing Location Others Reason for change: 1. New release of part numbers to have a piece of tape added for PIP improvement. We will be adding a "T" at the end of the part descriptions to denote the top tape Proposed change: 1. Currently there are 12 part numbers in QAD without the top tape. We will release 8 new part numbers which will have the tape added. The new part descriptions will have a "T" at the end to denote the top 2. Here's list of part numbers affected and their replacement: DRAWING # REPLACEMENT REPLACEMENT P/N DRAWING # P/N N324021 N324000 TL3240F160R TL3240F160RT N324001 TL3240F160G N324022 TL3240F160GT N324002 TL3240F160B N324023 TL3240F160BT N324003 TL3240F100R N324024 TL3240F100RT N324004 TL3240F100G N324025 TL3240F100GT N324005 TL3240F100B N324026 TL3240F100BT N324006 TL3240F260R N324027 TL3240F260RT N324007 TL3240F260G N324016 TL3240F260GT N324008 TL3240F260B N324017 TL3240F260BT N324009 TL3240F160Y N324028 TL3240F160YT N324010 TL3240F100Y N324029 TL3240F100YT N324011 TL3240F260Y N324030 TL3240F260YT Proposed Transition/change over: 1. This will be a running change until all inventory is used up of the 12 original part numbers. All future orders will be placed for the new parts. **Customer Notification** Action Item:



<u>www.e-switch.com</u> 800.867.2717