Product/Process Change Notifications



PCN - 15 112

| <u> </u> | | | | Re | elease Date: | October | 21 | 2015 |
|----------------------------|---|-------------------------------|------|----|--------------|---------|----|------|
| Product Name: | SAS and SATA receptacles | | | | | | | |
| | SAS and SATA receptacles | | | | | | | |
| Product Manager: | Ng Kok Chin | | | | | | | |
| Subject: | Notification of Change with Immediate Effectivity | | | | | | | |
| Distribution: | General | | | | | | | |
| Type of Change: | Packaging Change | | | | | | | |
| Change Description: | To make chamfer in one corner of the tray to prevent wrong orientation. Before – Radius edge After – Chamfer edge | | | | | | | |
| Reason for Change: | To prevent wrong orientation of tray in the packing machine | | | | | | | |
| Affected Parts: | Refer to part number list | | | | | | | |
| Effective Date of Change: | Nover | mber 1, 2 | 2015 | | | | | |
| Last Time Buy Date: | NA | | | | | | | |
| Last Disty Return Date: | | NA | | | | | | |
| Last Time Shipment Date | NA | | | | | | | |
| Datasheet Attached? | NA | | | | | | | |
| Qual/Test Data Attached? | NA | | | | | | | |
| Samples Availability Date: | November | 01 | 2015 | | | | | |
| Available Alternatives? | N/A | | | | | | | |
| Questions? | Contact your local FCI Representative, or Product Manager | | | | | | | |
| | Ng Kok Chin / Product Manager | | | | | | | |
| | +65-686061 | +65-68606182 / ngkoc @fci.com | | | | | | |

Note

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date. PCN is considered approved by the customer if no communication is received within 3 weeks