### HIROSE ELECTRIC CO., LTD.

2-6-3 Nakagawa Chuoh, Tsuzuki-ku, Yokohama, JAPAN

### **Product Change Notification**

We are writing today to inform you that we will make some changes as shown in the subject for the reason described below. We will announce them in advance.

1	Products affected	Please refer to Attachment 1.	
2	Replacement product	Please refer to Attachment 1.	
3	Classification of change	Material change. / Discontinued sales.	
4	Changes Change the materials to TSCA compliant materials. These changes will not affect the performances of the product.		
5 Reason for change		<ul> <li>Material change</li> <li>To comply with TSCA (US Hazardous Substances Regulation), which was added as a banned substance from March 8, 2021.</li> <li>Discontinued sales</li> <li>To the demand for the products is very low and stable supply is difficult.</li> </ul>	
6	Date of final reception of orders for the current product	September 30, 2021	
7	Date of the first reception of orders for the replacement product	July 30, 2021	
8	Date of final shipment of the current product		
9 Date of your acknowledgement By August 31, 2021		By August 31, 2021	

We kindly request that you inform Hirose business representative of your acknowledgement by the aforesaid date.

In the absence of a response by this date, please be advised that replacement product that described above will be delivered.

If you should have any questions, please feel free to contact a Hirose business representative.

Your understanding and cooperation are highly appreciated.

Attn.:

#### Product List PCN2021-11\_TSCA Material Change of Non-Compliant Produc and Discontinued Sales

	. I Current product		Replacement product		Remarks	
No.	Product code	Part Number	Product code	Part Number	Current product	Replacement product
1	211-0777-7-00	DE-9P-DC1	211-0777-7-16	DE-9P-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0778-0-00	DA-15P-DC1	211-0778-0-16	DA-15P-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0779-2-00	DB-25P-DC1	211-0779-2-16	DB-25P-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0780-1-00	DC-37P-DC1	211-0780-1-16	DC-37P-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0781-4-00	DD-50P-DC1	211-0781-4-16	DD-50P-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0782-7-00	DE-9S-DC1	211-0782-7-16	DE-9S-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0783-0-00	DA-15S-DC1	211-0783-0-16	DA-15S-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0784-2-00	DB-25S-DC1	211-0784-2-16	DB-25S-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0785-5-00	DC-37S-DC1	211-0785-5-16	DC-37S-DC1(16)	Not TSCA compliant	TSCA compliant
	211-0786-8-00	DD-50S-DC1	211-0786-8-16	DD-50S-DC1(16)	Not TSCA compliant	TSCA combiant
10	211-0700-0-00	00-300-001	211-0700-0-10	DD-300-DO1(10)	Not TOOA compliant	TSCA compliant
11	223-0088-1-50	D88-1-50 CTB-MJ-88SR(50) We have no plan to sell substitute products. We're sorry to cause any inconvenience to you.			-	-
		were sorry to cause a		ny inconvenience to you.		
	230-0105-7-50	DX-36S-DC2(50)	230-0105-7-16	DX-36S-DC2(16)	Not TSCA compliant	TSCA compliant
13	230-0106-0-50	DX-68S-DC2(50)	230-0106-0-16	DX-68S-DC2(16)	Not TSCA compliant	TSCA compliant
14	230-0264-0-50	DX-50S-DC2(50)	230-0264-0-16	DX-50S-DC2(16)	Not TSCA compliant	TSCA compliant
	230-0305-6-50	DX-20S-DC2(50)	230-0305-6-16	DX-20S-DC2(16)	Not TSCA compliant	TSCA compliant
	230-5128-0-50	DXM-26S-DC2(50)	230-5128-0-16	DXM-26S-DC2(16)	Not TSCA compliant	TSCA compliant
17	250-0010-7-00	CTB#シイレセツタ ンコウク			-	-
18	250-0233-1-00	PX50-SC-TC	1		-	-
19	250-0237-2-00	QR/P17-TC	1		-	-
20	301-0035-6-43	UG-29B/U(43)	1		-	-
21	302-0001-0-55	UG-88/U(55)	1		-	-
22	302-0025-9-48	UG-274/U(48)	1		-	-
23	302-0025-9-55	UG-274/U(55)	1		-	-
24	302-0039-3-48	BNC-A-JJ(48)	1		-	-
	313-0308-7-40	TNC-J-1.5DW-2(40)	1		-	-
26	313-0349-4-40	TNC-J-1.5DW-5(40)	1		-	-
27	313-0356-0-40	TNC-J-1.5DV-5(40)	We have no plan to s	ell substitute products.	-	-
28	321-3996-2-01	TNCBPJ-SFL2-FHSB-T-290RS	We're sorry to cause a	ny inconvenience to you.	-	-
	321-4012-7-01	TNCBPJ-H.FL-111-(100)RS	í ,	, ,	-	-
	321-4185-5-01	TNCBPJ-S.FL2-FHSB-250ARS	1		-	-
31	353-0097-2-52	BNC-TMP-05-2(52)	1		-	-
32	353-0098-5-52	BNC-TMJ-05-2(52)			-	-
33	572-1018-6-00	FX2C-40S-DC			-	-
34	701-0066-2-40	HRFC-C2(40)	1		-	-
35	701-0071-2-51	HRFC-PA11-G1(51)	1		-	-
36	704-0102-3-40	HSCJ-HSTJ-B(40)	1		-	-
37	704-5013-2-00	HSC-HA3-D1	1		-	-
	704-5014-5-00	HSC-HB3-D1	1		-	-
	709-0208-6-01	MF25S-WRF02-0203(01)	709-0208-6-16	MF25S-WRF02-0203(16)	Not TSCA compliant	TSCA compliant
	709-0209-9-01	MF25S-WP14S02-0203(01)	709-0209-9-16	MF25S-WP14S02-0203(16)	Not TSCA compliant	TSCA compliant
	709-0305-2-00	MF13S-WRFB01-0203	709-0305-2-16	MF13S-WRFB01-0203(16)	Not TSCA compliant	TSCA compliant
42	709-0311-0-00	MF13SDRFS-L3248-1M	We have no plan to sell substitute products.		-	
72	+2 109-0311-0-00 MF135DRF5-L3240		We're sorry to cause any inconvenience to you.			
43	709-0312-0-00	MF13SDRFS-L3248-0.5M	709-0312-0-16	MF13SDRFS-L3248-0.5M(16)	Not TSCA compliant	TSCA compliant * We will also change from SABIC material to Toray
						material, which we contacted at 430-18025.
44	709-0317-0-00	MF13SWPSC-T8334-75M	709-0317-0-15	MF13SWPSC-T8334-75M(15)	Not TSCA compliant	TSCA compliant
	709-0317-0-01	MF13SWPSC-T8334-100M	709-0317-0-16		Not TSCA compliant	TSCA compliant
	709-0318-0-00	MF13SWPLC-T8334-75M	709-0318-0-15	MF13SWPLC-T8334-75M(15)	Not TSCA compliant	TSCA compliant
	709-0318-0-01	MF13SWPLC-T8334-100M	709-0318-0-16		Not TSCA compliant	TSCA compliant
	709-0585-0-01	ME25S-WP14S01-0203(01)	709-0585-0-16	ME25S-WP14S01-0203(16)	Not TSCA compliant	TSCA compliant
49	709-0588-9-11	MF25S-WP12S02-0203(11)	709-0588-9-16	MF25S-WP12S02-0203(16)	Not TSCA compliant	TSCA compliant
	709-0596-7-00	MF25S-WP13S03-0203	709-0596-7-16	MF25S-WP13S03-0203(16)	Not TSCA compliant	TSCA compliant
		MF25S-WP18S02-0203(01)	709-0606-9-16	MF25S-WP18S02-0203(16)	Not TSCA compliant	TSCA compliant
51	709-0606-9-01					
51 52	709-0606-9-01 709-0606-9-11 750-0039-0-00	MF253-WP18302-0203(01) MF25S-WP18S02-0203(11) MF13SDPM-Q-2M	709-0606-9-17 750-0039-0-16	MF25S-WP18S02-0203(17) MF13SDPM-Q-2M(16)	Not TSCA compliant Not TSCA compliant	TSCA compliant TSCA compliant

PCN2021-11 2021

**Acknowledgement** 

(Customer → Hirose Electric business representative)

# Product Change Notification Request for Your Acknowledgement

We acknowledge the changes and schedule of this notification.

Customer's name:

-----

Acknowledgement stamp (or signature):

HIROSE ELECTRIC CO., LTD.

(Cut on this line)

PCN2021-11 2021

\_ \_

**Document Receipt** 

(Customer  $\rightarrow$  Hirose Electric business representative)

## Product Change Notification Request for Your Acknowledgement

We received the document concerning the above.

Customer's name:

Acknowledgment stamp (or signature):

HIROSE ELECTRIC CO., LTD.