Date:

Attn.:

HIROSE ELECTRIC CO., LTD.

2-6-3 Nakagawa Chuoh, Tsuzuki-ku, Yokohama, JAPAN

Notification of additional production site for Malaysian factory products

We applied for an additional production site in Indonesia in the past, but it takes time to receive approval from the related customers. We would like to inform you again.

- 1 Applicable products
 Please refer to the attached product list.
- 2 Additional production site. Because our Malaysian factory was suspended in 2020 due to the influence of COVIT-19 and the operation restriction order by Malaysian government, connector supply shortage was caused. And we are still subject to employment restrictions.

On the other side, we received many requests for BCP from our customers. As Indonesia government has different policies prioritizing economic activities and lenient restrictions, we started equipment production and already started production of some products in Indonesia factory with BCP requests.

- 3 Timing of additional production site
 The production of some products already started in Indonesia factory from February 2021.
- 4 Your acceptance
 We would like you to inform Hirose business representative of your approval by the end of May, 2021.

If you should have any questions, please feel free to contact Hirose business representative. Your understanding and cooperation are highly appreciated.

■ Product List PCN2021-12_Additional Production Site for Malaysian factory product:

No.	Product code	Part Number	Remarks
1	000 0070 0 50	TM5RC-44(50)	Production in Indonesia has started.
	222-0270-9-50		*This item is subject to material manufacturer change
			430-18025_SABIC. Production in Indonesia has started.
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	222-0337-8-50	TM5RC-66(50)	*This item is subject to material manufacturer change
		1 M31(C 00(30)	430–18025_SABIC.
			Production in Indonesia has started.
3	222-0338-0-50	TM5RC-64(50)	*This item is subject to material manufacturer change
		1	430-18025_SABIC.
			Production in Indonesia has started.
4	222-1242-9-71	TM5RF1-44(71)	*This item is subject to material manufacturer change
			430-18025_SABIC.
5	222-1363-3-50	TM5RJ3-44(50)	Production in Indonesia has started.
_	222-1378-0-50	TM11R-5C-88(50)	Production in Indonesia has started.
Ь			*This item is subject to material manufacturer change
-	222-1459-0-50	TM5RJ2-44(50)	430-18025_SABIC. Production in Indonesia has started.
	222-1459-0-50	TM5RJ2-64(50)	Production in Indonesia has started.
	222-1460-0-52	TM5RJ2-64(52)	Production in Indonesia has started.
	222-1461-2-50	TM5RJ2-66(50)	Production in Indonesia has started.
-	222-1462-5-50	TM5RJ2-88(50)	Production in Indonesia has started.
12	222-1463-8-50	TM5RJ3-64(50)	Production in Indonesia has started.
	222-1464-0-50	TM5RJ3-66(50)	Production in Indonesia has started.
	222-1464-0-51	TM5RJ3-66(51)	Production in Indonesia has started.
15	222-1465-3-50	TM5RJ3-88(50)	Production in Indonesia has started.
			Production in Indonesia has started.
16	222-1465-3-51	TM5RJ3-88(51)	*This item is subject to material manufacturer change
			430-18025_SABIC. Production in Indonesia has started.
17	222-1465-3-52	TM5RJ3-88(52)	*This item is subject to material manufacturer change
''	222 1403 3 32	1 W31(03 88(32)	430–18025_SABIC.
18	222-1486-3-50	TM5RJ2-62(50)	Production in Indonesia has started.
	222-1487-6-50	TM5RJ3-62(50)	Production in Indonesia has started.
		TM5RC-1212(50)	Production in Indonesia has started.
20			*This item is subject to material manufacturer change
			430-18025_SABIC.
. .			Production in Indonesia has started.
21	222-1513-4-51	TM5RC-1212(51)	*This item is subject to material manufacturer change
			430–18025_SABIC.
22	222-2148-6-50	TM11R-5C-66(50)	Production in Indonesia has started. *This item is subject to material manufacturer change
22	222 2140 0 30	TWITTK 3C 00(30)	430–18025_SABIC.
23	222-2578-5-50	TM5RC-1212-1.2(50)	Production in Indonesia has started.
_ <u>-</u> -	1 2 2 2	1=1= 11=(00)	Production in Indonesia has started.
24	222-5002-7-50	TM5RFX-44(50)	*This item is subject to material manufacturer change
			430-18025_SABIC.
			Production in Indonesia has started.
25	222-5081-3-50	TM5RJ2X-66(50)	*This item is subject to material manufacturer change
	000 5000 0 50	TMED 101/ 00/501	2020-08_FY2020 Discontinued Sales of Connector.
26	222-5082-6-50	TM5RJ2X-88(50)	Production in Indonesia has started.
0.7	222-5085-4-50	TM5RJ3X-64(50)	Production in Indonesia has started.
2/			*This item is subject to material manufacturer change 2020-08_FY2020 Discontinued Sales of Connector.
28	222-5087-0-50	TM5RJ3X-88(50)	Production in Indonesia has started.
		1 HOTOOX 00(00)	Production in Indonesia has started.
29	222-5133-5-50	TM11RX-5C-88(50)	*This item is subject to material manufacturer change
4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28			430-18025_SABIC.

30	222-0590-0-50	TM2RE-2416(50)	We will start production in Indonesia.
"		11112112 2110(00)	We will start production in Indonesia.
31	222-0591-2-50	TM2RE-1806(50)	*This item is subject to material manufacturer change
	222 0001 2 00	1 WZ 1 1 0 0 0 (0 0)	430–18025_SABIC.
32	222-0592-5-50	TM2RE-1204(50)	We will start production in Indonesia.
	222-0681-3-50	TM2REA-1212(50)	We will start production in Indonesia.
33	222 0001 3 30	TIMENEA 1212(30)	We will start production in Indonesia.
34	222-0737-6-50	TM2REA-1818(50)	*This item is subject to material manufacturer change
34	222-0737-0-30	TM2REA-1818(30)	430–18025_SABIC.
35	222-0749-5-50	TM2REA-2416(50)	We will start production in Indonesia.
	222-0749-3-30	TM2REA-2424(50)	We will start production in Indonesia.
	222-0751-7-50	TM2RE-2424(50)	We will start production in Indonesia.
38	222-0756-0-50	TM2RE-1208(50)	
	222-0757-3-50	TM2RE-1212(50)	We will start production in Indonesia.
39	222-0737-3-30	TM2RE-1212(30)	We will start production in Indonesia.
40	000 0706 5 50	TMODE 1010/50)	We will start production in Indonesia.
40	222-0796-5-50	TM2RE-1818(50)	*This item is subject to material manufacturer change
41	000 0707 0 50	TM0DE 0400(E0)	430-18025_SABIC.
41	222-0797-8-50	TM2RE-2408(50)	We will start production in Indonesia.
40	222_0700_0_50	TMODEA 1010/50\	We will start production in Indonesia.
42	222-0798-0-50	TM2REA-1812(50)	*This item is subject to material manufacturer change
40	000 0700 0 50	TAADDE A 1000/F0)	430-18025_SABIC.
	222-0799-3-50 222-0800-0-50	TM2REA-1208(50) TM2REA-2408(50)	We will start production in Indonesia.
44	222-0800-0-30	TM2REA-2408(50)	We will start production in Indonesia.
1 4 5	222-0801-3-50	TM2DEA 1006(F0)	We will start production in Indonesia.
45	222-0801-3-30	TM2REA-1806(50)	*This item is subject to material manufacturer change
40	000 0000 0 50	TMODE A 1004/F0)	430-18025_SABIC.
46	222-0802-6-50	TM2REA-1204(50)	We will start production in Indonesia.
47	000 1010 0 50	TMODA 00/50)	We will start production in Indonesia.
47	222-1012-9-50	TM3RA-88(50)	*This item is subject to material manufacturer change
			430-18025_SABIC.
40	222 1012 0 50	TM2DA 00/50)	We will start production in Indonesia.
48	222-1012-9-58	TM3RA-88(58)	*This item is subject to material manufacturer change 430-18025 SABIC.
40	222-1277-3-50	TM2REA-0602(50)	We will start production in Indonesia.
<u>49</u> 50	222-1286-4-50	TM2RE-0602(50)	We will start production in Indonesia.
51	222-1391-9-50	TM2RE-0604(50)	We will start production in Indonesia.
52	222-1422-0-50	TM2RE-0606(50)	We will start production in Indonesia.
53	222-1466-6-50	TM2REA-0604(50)	We will start production in Indonesia.
	222-1467-9-50	TM2REA-0606(50)	
1 34	LLL 1401-3-30	TWIZILA 0000(30)	We will start production in Indonesia. We will start production in Indonesia.
55	222-2850-0-50	TM11R-5C-62(50)	*This item is subject to material manufacturer change
35	222-2030-0-30		430–18025_SABIC.
56	222-3821-7-50	TM2REA-1210-64(50)	We will start production in Indonesia.
100	ZZZ 30Z1-/-30		We will start production in Indonesia.
57	222-5018-7-50	TM2REAX-1204(50)	*This item is subject to material manufacturer change
"	222 3010-7-30	1 WZNLAX 1204(30)	2020–08_FY2020 Discontinued Sales of Connector.
		+	We will start production in Indonesia.
58	222-5024-0-50	TM2REAX-2408(50)	*This item is subject to material manufacturer change
1 30	222-3024-0-30		
\vdash		+	2020-08_FY2020 Discontinued Sales of Connector.
59	222-5025-2-65	TM2DEAY_2416(65)	We will start production in Indonesia.
39	222-5025-2-65	TM2REAX-2416(65)	*This item is subject to material manufacturer change
<u> </u>			2020-08_FY2020 Discontinued Sales of Connector. We will start production in Indonesia.
60	222-5034-3-50	TM2DAY_00(50)	1
00	ZZZ-JU34-3-3U	TM3RAX-88(50)	*This item is subject to material manufacturer change
-		+	430-18025_SABIC. We will start production in Indonesia.
			*This item is subject to material manufacturer change
61	222-5136-3-20	TM5RE3VX-1212(20)	430–18025_SABIC and 2020–28_Material change for
			_
			products using PBT manufactured by Toyobo Co., Ltd.

Acknowledgement

(Customer → Hirose Electric business representative)

Notification of additional production site for Malaysian factory products

We acknowledge the changes and schedule of this notification.	
Customer's name:	
Acknowledgement stamp (or signature):	
HIROSE ELECTRIC CO.,	LTD.
(Cut on this line)	
PCN20	0 <u>21-12</u> 2021
Document Receipt	
(Customer $ ightarrow$ Hirose Electric business represen	tative)
Notification of additional production site for Malaysian factor products	<u>ry</u>
We received the document concerning the above.	
Customer's name:	
Acknowledgment stamp (or signature):	