JKL COMPONENTS Item Obsolescence Notice

CUSTOMER	CUSTOMER DRAWING NUMBER		REV. NO.	TODAYS DATE
Digi-key Corporation	289-1067-ND (JKL BXC-10655)			12/18/2017
CUSTOMER CONTACT NAME	TITLE		PHONE NO./EXT	
JKL PART NUMBER	PART DESCRIPTION		FAX NO.	
BXC-10655	Output harness connector for obsolete JKL inverter BXA-12549			
JKL CONTACT NAME Sherry Carpenter	PHONE 818-896-0019	EMAIL: <u>scarpenter@jkl</u>	EMAIL: scarpenter@jkllamps.com	

REASON FOR NOTICE:

This connector was being produced as an accessory item for JKL inverter BXA-12549

The inverter has become obsolete and the connector is no longer being produced due to lack of demand.

Obsolete Item:	Suggested Replacement Item:
289-1067-ND (JKL BXC-10655)	This item is made up of the following materials:
	24 AWG wire
	Mitsumi connector M63M83-06
	Mitsumi Crimp M63C84-1