



Kingbright Group  
China Factory

## Product End-Of-Life Notification

EOL Number:S202105002	Date:2021-05-04
Author:Ziven Ni	Issued By:SMD Technical Dept

Product Description & Replacement:	
Obsolete Part Number	APHHS1005PBC/A
Replacement Part Number	APHHS1005QBC/D

Reason for EOL:	Supply shortage from the chip supplier.
Last Time Buy Date:	N/A
Last Ship Date:	N/A

Approved By: Benson Huang

Title: Sr Quality manager

Date:2021-05-04

## Process/Engineering Change Notification Form

Please address your comments, if any, to your sales contact or quality assurance manager at Kingbright.

Notification Number: S202111001	Issue Date: 11/2/2021
Author: Ziven Ni	Issued By: SMD Technical Dept

Product Types:	Old P/N	New P/N
	APG1005VGC-T-5MAV	APG1005ZGC-5MAV
Change Category:	Part number	
Change Description:	LED chip change	
Reason for Change:	Because the lead time of Green chip used in the old P/N is drastically increased by the chip supplier without a confirmed delivery date, suggest customer to evaluate and change to the recommended new P/N using Green chip from a different supplier to ensure a stable supply.	
Anticipated impact of change:	Refer to the datasheet for detailed characteristic differences.	
Disposition of Old Product:	Customer may continue to consume the remaining inventory if any.	
Identification of Changed Product:	Refer to the new part number.	
Proposed First Ship Date:	Standard lead time after customer approves the new part numbers.	

Approved By: Benson Huang	Title: Sr Quality manager	Date: 11/2/2021
---------------------------	---------------------------	-----------------

Notification Number: S202111001

### Acknowledgement of Receipt of Notice

Company Name: \_\_\_\_\_

Name (please print): \_\_\_\_\_ Title: \_\_\_\_\_

Signature: \_\_\_\_\_ Date: \_\_\_\_\_