

Product Change Notification

PCN# 4-2017 DATE: 07/19/2017

PRODUCT(S) AFFECTED:

Laird Part Number	Old Rev	New Rev	Description
450-0075	4	5	RF Module, ProFLEX01-R2 U.FL
450-0076	4	5	RF Module, ProFLEX01-R2 F Antenna Module
450-0101	6	7	MGE, ProFLEX01-R2, Packaged Assy
450-0102	5	6	MGU, ProFLEX01-R2, Packaged Assy

DESCRIPTION OF CHANGE:

The firmware was updated to lower the CCA threshold for operation in the EU.

REASON FOR CHANGE:

Due to changes with the Radio Equipment Directive (RED) for Europe, the CCA threshold needed to be lowered to meet a test requirement.

ANTICIPATED IMPACT OF THE CHANGE:

None

METHOD OF IDENTIFYING THE CHANGED PRODUCT:

The new revision level is printed on the module labels.





Product Change Notification

PCN# 2-2017







FACTORY EFFECTIVITY DATE:

Parts with the new revision level will begin shipping in July.

CONTACT INFORMATION:

Headquarters Laird

50 S Main St., Suite 1100 Akron, OH 44308 USA Tel: 1(330) 434-7929 Fax: 1(330) 434-7931

PCN Contact pcn@lsr.com

Website www.lairdtech.com

Technical Support ews.support@lairdtech.com

Sales Contact cs-sales@lairdtech.com

Product Change Notices (PCNs) will be distributed at the discretion of Laird. Occasionally, Laird may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.

