

Expertise Applied | Answers Delivered

8755 W . Higgins Road Suite 500 Chicago, IL 60631

www.littelfuse.com

May 17th, 2017 To: Valued Customer


From: Littelfuse Product Management

Subject: LFPCN41249 - Voltage Upgrade for 345 Series Panel Mount and PCB Mount Holders


Littelfuse Product Management would like to inform you that to better serve market needs, we are upgrading the operating voltage rating for 345 Series Panel Mount and PCB Mount Holders.

For the *0345 Panel Mount Series*: There is no change in design, form, or fit. The voltage rating is improved from 300 V up to 600 V for the 345 600, 345 700 and 345 900 Series; certified by UL/CSA. The voltage mark will be changed from "300 V" to "600 V" on the holder's plastic body. (Please see below for reference)

345 Series Panel Mount - Prior version




*Front side view




*Back side view

345 Series Panel Mount – New version



*Front side view




*Back side view

The affected part numbers are:

03450601H 03450601HX040 03450601X 03450601ZX010 03450602H 03450602HX040 03450602ZX010 03450603H 03450603HX040 03450603X 03450611H 03450611HX040 03450611X	03450612H 03450612HX040 03450612X 03450612ZX010 03450613H 03450613HX040 03450613X 03450613ZX010 03450621H 03450621X 03450622H 03450622H 03450622X 03450623H	03450631H 03450631X 03450632H 03450632X 03450633H 03450633X 03450701H 03450701HX040 03450701X 03450701ZX010 03450711H 03450711HX040 03450711X	03450903H 03450903HX040 03450903HXQC040 03450903X 03450903ZX010 03450913H 03450913HX040 03450913HXQC040 03450913X 03450913ZX010 03450923H 03450923X 03450923X
03450611X 03450611ZX010	03450623H 03450623X	03450711X 03450711ZX010	03450933H 03450933X


For the *0345 PCB Mount Series*: There is no change in design, form or fit. The voltage rating is improved to 600V certified by UL/CSA. The voltage mark will be changed from "250 V" to "600 V' on the holder's plastic body. VDE voltage will remain the same at "250 V". (Please see below for reference)

345 121 and 345 101 Series Prior version



*Front side view

345 121 and 345 101 Series New version



*Front side view

The affected part numbers are

03450101H 03450101HXAB010 03450101X 03450121H 03450101HX010 03450101HXB 03450101ZX010 03450121X

This change will be effective from July 17th, 2017

Please let us know, should you require any support or have any further queries.

Best Regards;

Global Product Manager

Electronics Business Unit