

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000688

DATE: 01-Jul-2011

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX6695AUB	MAX6695AUB+			Part reactivated from prior notice: M000671
Reactivation	MAX6695AUB+	N/A			Part reactivated from prior notice: M000671
Reactivation	MAX6695AUB+C5L	N/A			Part reactivated from prior notice: M000671
Reactivation	MAX6695AUB+T	N/A			Part reactivated from prior notice: M000671
Reactivation	MAX6695AUB-T	MAX6695AUB+T			Part reactivated from prior notice: M000671
Reactivation	MAX6695AUB-TG05	N/A			Part reactivated from prior notice: M000671
Reactivation	MAX6695YAUB+	N/A			Part reactivated from prior notice: M000671
Reactivation	MAX6695YAUB+T	N/A			Part reactivated from prior notice: M000671

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 01-Aug-2011