

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000874

DATE: 11-Sep-2018

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX4462UETT+	N/A			Part reactivated from prior notice: M000869
Discontinuance	78Q2120C09-CGTR/F	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	DS4106AN+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4106BN+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4125D+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4156D+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4156P+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4212BN+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4250D+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4250P+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4300D+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4311D+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4311P+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4425AN+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4425BN+	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4M125D+33	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4M133D+33	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	DS4M200D+33	N/A	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	MAX19700ETM+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX19705ETM+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX19706ETM+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX19708ETM+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX3243EEAI+C9V	MAX3243EEAI+	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX526CCWG+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX526CCWG+T	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX526CEWG+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured

Discontinuance	MAX526DCWG+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX526DCWG+T	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX526DEWG+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX527CCWG+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX527CEWG+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX527DCWG+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX527DCWG+T	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX527DEWG+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX9725EEBC+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX9725EEVKIT+	N/A	11-Sep-2018	11-Sep-2018	EVKIT is No Longer Supported
Discontinuance	MAX9830AETA+	MAX98300ETA+	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX9830AEVKIT+	MAX98300ETA+T	11-Sep-2018	11-Sep-2018	EVKIT is No Longer Supported
Discontinuance	MAX98400BETG+	MAX98400AEVKIT+	11-Sep-2019	12-Mar-2020	The eval kit is no longer supported
Discontinuance	MAX98500EVKIT+	N/A	11-Sep-2018	11-Sep-2018	EVKIT is No Longer Supported
Discontinuance	MAX98500EWE+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX98500EWE+T	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX98512SDEMBRD#	N/A	11-Sep-2018	11-Sep-2018	EVKIT is No Longer Supported
Discontinuance	MAX9856ETL+	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX9856ETL+T	N/A	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX9856EVKIT+	N/A	11-Sep-2018	11-Sep-2018	EVKIT is No Longer Supported
Discontinuance	MAX98724AENX+	N/A	11-Sep-2019	12-Mar-2020	The part was not released
Discontinuance	MAX98724AENX+T	N/A	11-Sep-2019	12-Mar-2020	The part was not released
Discontinuance	MAX98728AENX+	MAX98728BENX+T	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX98728AENX+G7	MAX98728BENX+G7	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX98728AENX+T	MAX98728BENX+T	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX98728AENX+TG7	MAX98728BENX+TG7	11-Sep-2019	12-Mar-2020	Part can no longer be manufactured
Discontinuance	MAX98740AENL+	MAX98740BENL+T	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	MAX98740AENL+G7	MAX98740BENL+G7	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	MAX98740AENL+T	MAX98740BENL+T	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	MAX98740AENL+TG7	MAX98740BENL+TG7	11-Sep-2018	11-Sep-2018	Part can no longer be manufactured
Discontinuance	MAX98927SDEMBRD#	N/A	11-Sep-2018	11-Sep-2018	EVKIT is No Longer Supported
Discontinuance	MAX98932SDEMBRD#	N/A	11-Sep-2018	11-Sep-2018	EVKIT is No Longer Supported
Discontinuance	MAX98937SEVSYS#	MAX98937SDEMBRD#	11-Sep-2018	11-Sep-2018	EVKIT is No Longer Supported