

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000964I

DATE: 17-Mar-2019

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommeded Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------------|--------------------|------------------------|-----------------|--------------------|--|
| Reactivation | MAX15025BATB+T | N/A | | | Part reactivated from prior notice: M000926I |
| Lead-Free Conversion | MAX4007EUT-T | MAX4007EUT+T | 17-Mar-2019 | 17-Mar-2019 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX4245AXT | MAX4245AXT+T | 17-Mar-2019 | 17-Mar-2019 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX4380EXT | MAX4380EXT+T | 17-Mar-2019 | 17-Mar-2019 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX4481AXT | MAX4481AXT+T | 17-Mar-2019 | 17-Mar-2019 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX5400EKA | MAX5400EKA+T | 17-Mar-2019 | 17-Mar-2019 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX5474EKA-T | MAX5474EKA+T | 17-Mar-2019 | 17-Mar-2019 | Part is leaded. Request information on lead-free version |
| Discontinuance | ADC0820CCM+TG002 | ADC0820CCM+T | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | DS1080LU/T+A00 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | ICM7240C/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | ICM7242I/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | ICM7250C/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | ICM7260C/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | LM4050AEUM3-4.1/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX11633EVKIT# | MAX11633EVSYS# | 17-Mar-2019 | 17-Mar-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX1231BEVKIT# | MAX1231BEVSYS# | 17-Mar-2019 | 17-Mar-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX13030EETE/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX13030EETE/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX13184EESD+ | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX13184EESD+T | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX1455C/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX14611EETD+ | MAX14611ETD+ | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX14611EETD+T | MAX14611ETD+T | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16123WTDQQ0+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16123WTDQQ0+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132B17N/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |

| Diagontinuanas | MAV46422D47N///-T | NI/A | 17 Mar 2010 | 17 Mar 2010 | The next wee not released |
|----------------|-------------------|------|-------------|-------------|---------------------------|
| Discontinuance | MAX16132B17N/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132F122A/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132F122A/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132J46B/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132J46B/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132OM31/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132OM31/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132W29A/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16132W29A/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16133FHA/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16133FHA/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16133INH/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16133INH/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16133OAM/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16133OAM/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16133VFN/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16133VFN/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16134MLG/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16134MLG/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16134OAM/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16134OAM/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16134SKD/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16134SKD/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16134TDA/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16134TDA/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16135HSB/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16135HSB/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16141ATD/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16141ATD/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16143WAUK+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16143WAUK+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16145WAUK+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16145WAUK+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16147WAUK+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16147WAUK+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX16149WAUK+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |

| Discontinuance | MAX16149WAUK+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
|----------------|--------------------|---------------|-------------|-------------|---|
| Discontinuance | MAX250CSD+TG55 | MAX250CSD+T | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX3362AC/W-CF9 | MAX3362AESA+ | 17-Mar-2019 | 17-Mar-2019 | Leaded with a Lead-Free or RoHS Replacement |
| Discontinuance | MAX4006EUT | N/A | 17-Mar-2019 | 17-Mar-2019 | Leaded with a Lead-Free or RoHS Replacement |
| Discontinuance | MAX44294ASD+T | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX5316EVKIT# | MAX5316EVSYS# | 17-Mar-2019 | 17-Mar-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX6070BAUT/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6070BAUT/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6315US31D2/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6315US31D2/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6381XR29D2/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6381XR29D2/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6389XS32D2/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6389XS32D2/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6394US317D1/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6394US317D1/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6394US470D1/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6394US470D1/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6414UK18/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6414UK18/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6414UK44/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6414UK44/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6501UKP095+TG52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX6653EVSYS | N/A | 17-Mar-2019 | 17-Mar-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX6655EVSYS | N/A | 17-Mar-2019 | 17-Mar-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX6660EVSYS | N/A | 17-Mar-2019 | 17-Mar-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX6681EVSYS | N/A | 17-Mar-2019 | 17-Mar-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX6769TALD2/VY+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6795TPLD3/V+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX6795TPLD3/V+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX809REUR+G52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX809REUR+TG52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX809SEUR+G096 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX809SEUR+G52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX809SEUR+TG096 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX809SEUR+TG52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |

| Discontinuance | MAX811TEUS+G52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
|----------------|-------------------|------------------|-------------|-------------|--|
| Discontinuance | MAX811TEUS+TG52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX823SEUK+G52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX823SEUK+TG52 | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX9065AEBS+G45 | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX9065AEBS+TG45 | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX912C/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX921C/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX923C/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX941C/D | N/A | 17-Mar-2019 | 17-Mar-2019 | Part can no longer be manufactured |
| Discontinuance | MAX9704EVKIT+TQFP | N/A | 17-Mar-2019 | 17-Mar-2019 | EVKIT is No Longer Supported |
| Discontinuance | MAX9938FEBS+ | MAX9938FEBS+G45 | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX9938FEBS+T | MAX9938FEBS+TG45 | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX9938TEBS+T | MAX9938TEBS+TG45 | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAX9938WEBS+ | MAX9938WEBS+G45 | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAXM10000ALJ+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAXM10002ALI+ | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |
| Discontinuance | MAXM10002ALI+T | N/A | 17-Mar-2019 | 17-Mar-2019 | The part was not released |