

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000984I

DATE: 29-Feb-2020

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS2741N+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	DS2741N+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX1022BETX+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX11324ATJ+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX14717EWC+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX1518BETJ+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX1518BETJ+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX15511IGTL+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX15567ETG+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX16091UK16IOA+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX16091UK29AHC+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX16091UK46FKC+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX1645AEEI+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX1645AEEI+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX16826ATJ/VY+	MAX16826ATJ/V+	28-Feb-2021	27-Aug-2021	The part was not released
Discontinuance	MAX16826ATJ/VY+T	N/A	28-Feb-2021	27-Aug-2021	The part was not released
Discontinuance	MAX17016ETL+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX17016ETL+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX17108ETI+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX17528GTJ+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX19192ETI+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX19192ETI+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX3130EAI+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX31912AUI+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX31912AUI+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX3456EEUD+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured

D'	MANO AFOFFLID. T	11/0	00 14 0000	07 Avv 0000	Dout and a leasure has a sector of
Discontinuance	MAX3456EEUD+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX3773CEE+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX3773CEE+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX4008EUT+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX4008EUT+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX4519CEE+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX4519CEE+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX4563CEE+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX4571CAI+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX545BCSD+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX545BCSD+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6339MUT+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6379UR44+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6386XS29D1+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6386XS29D1+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6390XS26D7+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6390XS26D7+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6392KA23+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6703MKA+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6703MKA+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6718AUKRVD3+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6718AUKRVD3+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6740XKWGD3+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6744XKSVD3+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6753KA28/V+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6753KA28/V+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6934ATH+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8555AEUB+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8555AEUB+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8716ETG+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8857AETL+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8857AETL+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8878EUK36+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8883EUTA5+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8999YEXT18+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX9324EUP+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured

Discontinuance MAX9324EUP+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured