



Date: Nov 15, 2022

PCN No#: 111522-1

PCN Title: Products End of Life Notification

Dear Customer:

This is an announcement of End of Life products that are currently being offered by Micro Commercial Components Corp(MCC) .We request that you acknowledge receipt of this notification within 30 days of the date of this PCN. Please refer to the implementation date of this change as it is stated in the attached PCN form. Please contact your local sales representative to acknowledge receipt of this PCN.

If you have any questions about PCN's products, please contact your local sales representative.

Sincerely,

MCC PCN Team



Products End of Life Notification

Notification Date	Implementation Date	Last Time Buy Date	Last Time Ship Date	Change Type	PCN No
Nov 15, 2022	Feb 15, 2023	Feb 15, 2023	May 15, 2023	Products End of Life (EOL)	111522-1
TITLE					
Products End of Life Notification					
DESCRIPTION OF CHANGE					
MCC has undergone a review of its core business and products , and determined to discontinue below product.This PCN is being issued to notify customers that products listed below will no longer be available from MCC. For select products on this PCN, replacement parts are being offered and are available for immediate substitution. Please contact your local representatives for any questions or additional information.					
IMPACT					
Table 1: EOL Devices With Possible Replacement Parts. Table 2: EOL Devices Without Possible Replacement Parts.					
PRODUCTS AFFECTED					
See Table 1 ~ 2.					
WEB LINKS					
Terms And Conditions:		https://www.mccsemi.com/Home/TermsAndConditions			
For More Information Contact:		https://www.mccsemi.com/Contact/Index			
Products:		https://www.mccsemi.com/ProductCategories			
DISCLAIMER					
Unless a MCC Sales representative is contacted in writing within 30 days of the posting of this notice, all changes described in this announcement are considered approved.					

Table 1 - EOL Devices With Possible Replacement Parts

EOL Parts	Possible Replacements	EOL Parts	Possible Replacements	EOL Parts	Possible Replacements
MCAC85N06Y-TP	MCA95N06Y-TP	MCU05N20-TP	MCU05N20A-TP	SI3134KDW-TP	SI3134KDWA-TP
MCAC16N03-TP	MCAC40N03A-TP	MCU04N60A-TP	MCU05N60A-TP	SI3134KDW-TP-HF	SI3134KDWA-TP
MCAC16N03-TP-HF	MCAC40N03A-TP	MCU12P06-TP	MCU12P06Y-TP	SI3134KL3-TP	SI3134KL3A-TP
MCP150N06A-BP	MCB145N06Y-BP	MCU18N20-TP	MCU18N20A-TP	SI3134KW-TP	SI3134KWA-TP
MCG10P03-TP	MCG20P03-TP	MCU18N20-TP-HF	MCU18N20A-TP	SI3139KDW-TP	SI3139KDWA-TP
MCG10P03-TP-HF	MCG20P03-TP	MCU20N06-TP	MCU20N06B-TP	SI3139KDW-TP-HF	SI3139KDWA-TP
MCG16P03-TP	MCG20P03-TP	MCU40N10AHE3-TP	MCU45N10HE3-TP	SI3139KL3-TP	SI3139KL3A-TP
MCM1208-TP	MCM1261A-TP	MCU40N10-TP	MCU45N10-TP	SI3415B-TP	SI3415C-TP
MCM1216-TP	MCM1261A-TP	MCU50N03-TP	MCU50N03A-TP	SI3415B-TP-HF	SI3415C-TP
MCMN2014-TP	MCMN2014A-TP	MSJAC11N65Y-TP	MSJAC11N65B-TP	SI3439KDW-TP	SI3439KDWA-TP
MCP130N10Y-BP	MCP130N10YA-BP	MSJU11N65-TP	MSJU11N65A-TP	SIL04P06-TP	SIL04P06Y-TP
MCP130N10Y-BP-HF	MCP130N10YA-BP	MSJW20N65-BP	MSJW20N65A-BP	SIL04P06-TP-HF	SIL04P06Y-TP
MCPF18N20-BP	MCPF18N20A-BP	SI2324-TP	SI2324A-TP	SIL3439K-TP	SIL3439KA-TP
MCQ03P10Y-TP	MCQ05P10Y-TP	MCQ08N06-TP	MCQ08N06-TP	SIX3134K-TP	SIX3134KA-TP
MCQ15N10B-TP	MCQ15N10YA-TP	MCQ08N06-TP-HF	MCQ08N06-TP	SIX3139K-TP	SIX3139KA-TP
MCQ4459-TP	MCQ4435A-TP	UM6K1N-TP	UM6K1NA-TP	SIX3439K-TP	SIX3439KA-TP
MCQ4559-TP	MCQ4559A-TP	SI3134KLA-TP	SI3134KL3A-TP	SIX3439K-TP-HF	SIX3439KA-TP
SIL05N06-TP	SIL05N06A-TP	SI3139KW-TP	SI3139KWA-TP		

Table 2 - EOL Devices Without Possible Replacement Parts

MCPF07N65-BP	MCT06P02-TP	MCM1206-TP	MCCD2004-TP	MCCD2005-TP	MCCD2007-TP
MCCD2007A-TP	MCAC90N04-TP	MSJU07N65-TP	MCT08P06-TP	2N7002DWL-TP	SIL6321-TP
MCP07N65-BP	MCB145N15Y-TP				