



## Product Change Notification / RMES-26KYQW833

### Date:

22-Feb-2022

### Product Category:

Analog to Digital Converters, Battery Management and Fuel Gauges - Battery Chargers, Digital Potentiometers

### PCN Type:

Manufacturing Change

### Notification Subject:

CCB 4845 Final Notice: Qualification of UTL3 as an additional assembly site for selected MCP42xx, MCP46xx, MCP738xx and MCP34xx device families available in 10L DFN (3x3x0.9mm) package.

### Affected CPNs:

[RMES-26KYQW833\\_Affected\\_CPN\\_02222022.pdf](#)

[RMES-26KYQW833\\_Affected\\_CPN\\_02222022.csv](#)

### Notification Text:

**PCN Status:** Final notification

**PCN Type:** Manufacturing Change

**Microchip Parts Affected:** Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

**Description of Change:** Qualification of UTL3 as an additional assembly site for selected MCP42xx, MCP46xx, MCP738xx and MCP34xx device families available in 10L DFN (3x3x0.9mm) package.

### Pre and Post Change Summary:

	Pre Change	Post Change	
Assembly Site	UTAC Thai Limited (UTL-1) LTD.	UTAC Thai Limited (UTL-1) LTD.	UTAC Thai Limited (UTL-3)

	(NSEB)	(NSEB)	(UTL3)
<b>Wire material</b>	Au	Au	Au
<b>Die attach material</b>	8600	8600	8600
<b>Molding compound material</b>	G700LTD	G700LTD	G700LTD
<b>Lead frame material</b>	C194	C194	C194

**Impacts to Data Sheet:**

None

**Change Impact:**None

**Reason for Change:**To improve manufacturability and productivity by qualifying UTL3 as an additional assembly site.

**Change Implementation Status:**In Progress

**Estimated First Ship Date:**March 30, 2022 (date code: 2214)

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

**Time Table Summary:**

Workweek	September 2021					>	February 2022				March 2022			
	36	37	38	39	40		06	07	08	09	10	11	12	13
Initial PCN Issue Date					X									
Qual Report Availability									X					
Final PCN Issue Date									X					
Estimated Implementation Date														X

**Method to Identify Change:**

Traceability code

**Qualification Report:**Please open the attachments included with this PCN labeled as PCN\_#\_Qual\_Report.

**Revision History:**September 27, 2021: Issued initial notification.**February 22, 2022:** Issued final notification. Attached the Qualification Report. Provided estimated first ship date to be on March 30, 2022.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

**Attachments:**

[PCN\\_RMES-26KYQW833\\_Qual\\_Report.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

MCP4232-502E/MF  
MCP4232-103E/MF  
MCP4232-104E/MF  
MCP4232-503E/MF  
MCP4242-502E/MF  
MCP4242-103E/MF  
MCP4242-104E/MF  
MCP4242-503E/MF  
MCP4262-502E/MF  
MCP4262-103E/MF  
MCP4262-104E/MF  
MCP4262-503E/MF  
MCP4252-502E/MF  
MCP4252-103E/MF  
MCP4252-104E/MF  
MCP4252-503E/MF  
MCP4232T-502E/MF  
MCP4232T-103E/MF  
MCP4232T-104E/MF  
MCP4232T-503E/MF  
MCP4242T-502E/MF  
MCP4242T-103E/MF  
MCP4242T-104E/MF  
MCP4242T-503E/MF  
MCP4262T-502E/MF  
MCP4262T-103E/MF  
MCP4262T-104E/MF  
MCP4262T-503E/MF  
MCP4252T-502E/MF  
MCP4252T-103E/MF  
MCP4252T-104E/MF  
MCP4252T-503E/MF  
MCP4632T-502E/MF  
MCP4632T-103E/MF  
MCP4632T-104E/MF  
MCP4632T-503E/MF  
MCP4642T-502E/MF  
MCP4642T-103E/MF  
MCP4642T-104E/MF  
MCP4642T-503E/MF  
MCP4652T-502E/MF  
MCP4652T-103E/MF  
MCP4652T-104E/MF  
MCP4652T-503E/MF  
MCP4662T-502E/MF  
MCP4662T-103E/MF

MCP4662T-104E/MF  
MCP4662T-503E/MF  
MCP73833-6SI/MF  
MCP73833-AMI/MF  
MCP73833-B6I/MF  
MCP73833-BZI/MF  
MCP73833-CNI/MF  
MCP73833-DZI/MF  
MCP73833-FCI/MF  
MCP73833-G8I/MF  
MCP73833-GPI/MF  
MCP73833-HAI/MF  
MCP73833-NVI/MF  
MCP73833-YAI/MF  
MCP73834-6SI/MF  
MCP73834-B6I/MF  
MCP73834-CNI/MF  
MCP73834-FCI/MF  
MCP73834-G8I/MF  
MCP73834-GPI/MF  
MCP73834-NVI/MF  
MCP73834-YAI/MF  
MCP73833T-6SI/MF  
MCP73833T-AMI/MF  
MCP73833T-B6I/MF  
MCP73833T-BZI/MF  
MCP73833T-CNI/MF  
MCP73833T-DZI/MF  
MCP73833T-FCI/MF  
MCP73833T-G8I/MF  
MCP73833T-GPI/MF  
MCP73833T-HAI/MF  
MCP73833T-NVI/MF  
MCP73833T-YAI/MF  
MCP73834T-6SI/MF  
MCP73834T-B6I/MF  
MCP73834T-CNI/MF  
MCP73834T-FCI/MF  
MCP73834T-G8I/MF  
MCP73834T-GPI/MF  
MCP73834T-NVI/MF  
MCP73834T-YAI/MF  
MCP73837-FCI/MF  
MCP73837-FJI/MF  
MCP73837-NVI/MF  
MCP73838-FCI/MF  
MCP73838-FJI/MF  
MCP73838-NVI/MF  
MCP73837T-FCI/MF

MCP73837T-FJI/MF  
MCP73837T-NVI/MF  
MCP73838T-FCI/MF  
MCP73838T-FJI/MF  
MCP73838T-NVI/MF  
MCP3423-E/MF  
MCP3427-E/MF  
MCP3423T-E/MF  
MCP3427T-E/MF