




May 25, 2007

To: Molex Sales Engineers and Authorized Distributors


Subject: **Product Obsolescence**

Ref: Standard right angle modular jack series: **41369, 41687, 42063, 42118**

Please notify your customers that Molex will obsolete the standard right angle flush mount and flangeless modular jack series 41369, 41687, 42063 and 42118 due to the condition of the tooling and low volume requirements. Molex will do everything possible to support existing backlog, but it is highly recommended that qualification of one of the replacement parts begins immediately.



**Right Angle Flush Mount  
Series 41369 and 42063**



**Right Angle Flangeless  
Series 41687 and 42118**

#### **Obsolescence Detail**

- See page 2 for effected part numbers and replacement part numbers
- Last time buy date (orders received by): June 30, 2007
- Obsolescence date (orders shipped by): July 31, 2007

Please contact me if you have any questions.  
I apologize for the inconvenience this may cause.

Sara Stanford  
Product Manager  
630.527.4221  
sara.stanford@molex.com



Planned for Obsolescence			Replacement Part Information*				
Molex Series	Molex Part Number	Description	Molex 95009 Series Drop in Replacement	Low Profile Alternative		Tyco Cross	
41369	15437464	RA Flush TH 50"SAu 6/4	950092641				
	15437540	RA Flush TH 50"SAu 4/2					
	15437541	RA Flush TH 15"SAu 4/4	950092441				
	15437544	RA Flush TH 50"SAu 4/4	950092441				
	15437550	RA Flush TH 50"SAu 6/4	950092641				
	15437563	RA Flush TH 50"SAu 6/2		432496007			
	15437564	RA Flush TH 50"SAu 6/4	950092641	432496004			
	15437565	RA Flush TH 30"SAu 6/4	950092641	432496004			
	15437566	RA Flush TH 50"SAu 6/6	950092661	432496001			
	15437567	RA Flush TH 30"SAu 6/6	950092661	432496001			
	15437580	RA Flush TH 50"SAu 8/2					
	15437584	RA Flush TH 50"SAu 8/4					
	15437586	RA Flush TH 50"SAu 8/6	950092861	432498010			
	15437588	RA Flush TH 50"SAu 8/8	950092881	432498004			
	15437546	RA Flush TH 15"SAu 4/4	950092441				
	15437570	RA Flush TH 50"SAu 6/4	950092641	432496004			
	15437571	RA Flush TH 50"SAu 6/2					
	41687	15438541	RA Flgls TH 50"SAu 4/2			432024104	
		15438544	RA Flgls TH 50"SAu 4/4	950092447		432024101	
		15438561	RA Flgls TH 50"SAu 6/2		432496107	432026107	
15438564		RA Flgls TH 50"SAu 6/4	950092647	432496104	432026104		
15438566		RA Flgls TH 50"SAu 6/6	950092667	432496101	432026101		
15438584		RA Flgls TH 50"SAu 8/4		432498119	432028119		
15438586		RA Flgls TH 50"SAu 8/6	950092867	432498116	432028116		
15438588		RA Flgls TH 50"SAu 8/8	950092887	432498104	432028104		
15438589		RA Flgls TH 30"SAu 8/8	950092887	432498104	432028104		
15438590		RA Flgls TH 50"SAu 8/2			432028122		
42063	15439501	RA Flush Keyed 50"SAu 8/8			432028113	<a href="#">5520252-4</a>	
	50291736	RA Flush Keyed 50"SAu 8/8			432028113	<a href="#">5520252-4</a>	
	15439504	RA Flush Keyed 50"SAu 8/6					
	15439507	RA Flush Keyed 50"SAu 8/4					
	15439510	RA Flush Keyed 50"SAu 8/2					
42118	15438501	RA Flgls Keyed 50"SAu 8/8			432028113	<a href="#">5554517-1</a>	
	15438504	RA Flgls Keyed 50"SAu 8/6					
	15438507	RA Flgls Keyed 50"SAu 8/4					
	15438510	RA Flgls Keyed 50"SAu 8/2					

\* Customers should perform their own in depth cross reference verification to confirm compatibility of replacement part with their system.