

| Product Family | Mini-fit | 10653558 | |
|---|---|--------------------|--|
| | | GCN Number | |
| Series | 5569 & 44130 | September 17, 2014 | |
| | | Date Issued | |
| Reason For Change | New, Modified, Or Replacement Tooling | | |
| Change Description | This letter is to inform you that the existing tooling to make 5569-082 housings is worn beyond repair and will be replaced by new tooling. | | |
| | | | |
| Part Numbers Affected | Please refer to CustomerPartList.csv attached to e-mail message. | | |
| Reason For Short Notice Exception | | | |
| Assessment Of Change (How Product Will Be Qualified & Validated) | Product produced by the new tooling will be fully qualified by Molex before it is released to production. | | |
| Internal Molex Qualification Date (Planned Date Information Available) | January 29, 2015 | | |
| Sample Availability Date (Changed Part) | January 29, 2015 | | |
| Date of Implementation | March 18, 2015 | | |
| Method of Identifying Change | Product shipped after March 15, 2015 could contain housings from the new tooling | | |
| Recommended Replacement Parts | | | |
| Last Time Buy Date for Obsolete Parts | | | |
| Last Time Ship Date for Obsolete Parts | | | |

| Contact | Name | E-mail | Phone Number |
|---|---|----------------------------|-----------------|
| Sales Engineer | Please refer to e-mail message for your local sales engineer. | | |
| Regional Coordinator (Japan and Korea) | Naomi Maruyama | Naomi.Maruyama@molex.co.jp | +81-46-265-2416 |
| Regional Coordinator (Asia- excluding Japan and Korea) | Allen Yu | Allen.Yu@molex.com | +886-2-66251751 |
| Regional Coordinator (Europe, Middle East, Africa) | QuiNann Lim | QuiNann.Lim@molex.com | +31-40-295-8472 |
| Regional Coordinator (Americas) | Maria Sullivan | Maria.Sullivan@molex.com | 1-727-322-4352 |

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com