

Global Change Notification (GCN)

Product Family Impact 85 Ohm4P Daughtercard receptacle 10675941

GCN Number


Series various March 03, 2015


Date Issued

Reason For Change Product Component Change

Change Description

This letter is to inform you that in an effort for continuous improvements, Molex is implementing a running change on the following series: 170340 - Impact 850hm Plus 4P Daughtercard receptacle; 172056 - Impact 850hm Plus 4P Daughtercard receptacle without plus clip. The below pictures show the addition of plastic (in red) which improves the consistency of wafer-to-wafer spacing during the assembly process resulting in improved signal integrity performance.





Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception Assessment Of Change Qualification data upon request. (How Product Will Be Qualified & Validated) Internal Molex Qualification Date September 15, 2014 (Planned Date Information Available) Sample Availability Date February 11, 2015 (Changed Part) Date of Implementation September 14, 2015 Method of Identifying Change Visual inspection Recommended Replacement Parts N/A Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com