

## **Global Change Notification (GCN)**

Product Family	Ethernet	10686623	
		GCN Number	
Series	120312	May 19, 2015	
		Date Issued	
Reason For Change	Change Construction Or Material		
Change Description	The purpose of this letter is to inform you that we can not use Lock nut with current thickness 10mm as current vendor will not support and can only use 7mm. We cannot fulfil current orders in the system because of the above issue. Changing to 7mm will have no effect on fit, form, function of the end product.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-r	nail message.	
Reason For Short Notice Exception	Force Majeure		
Assessment Of Change (How Product Will Be Qualified & Validated)	Molex internal report		
Internal Molex Qualification Date (Planned Date Information Available)	April 30, 2015		
Sample Availability Date (Changed Part)	April 30, 2015		
Date of Implementation	May 15, 2015		
Method of Identifying Change	N/A		
Recommended Replacement Parts	n/a		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com