

## Global Change Notification (GCN)

Product Family	2 1/2IN OUTER RING HEATTREATED	10691643
		GCN Number
Series	130096-130097-130200	June 10, 2015
		Date Issued
Reason For Change	Supplier Change	
Change Description	This letter is to inform you that the Molex Industrial Products Group, Molex factory located in Juarez, Mexico will be adding a second source supplier for part numbers 1302000250 to maintain a continuous supply and to meet delivery expectations.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Force Majeure	
Assessment Of Change (How Product Will Be Qualified & Validated)	Qualification from first article inspection	
Internal Molex Qualification Date (Planned Date Information Available)	June 15, 2015	
Sample Availability Date (Changed Part)	June 15, 2015	
Date of Implementation	June 22, 2015	
Method of Identifying Change	Shipping label date	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)