

Global Change Notification (GCN)

Product Family	.062" pin and Socket Receptacle	10699639	
		GCN Number	
Series	1625, 1772, 5025	August 04, 2015	
		Date Issued	
Reason For Change	Obsolescence		
Change Description	This letter is to announce that housing series 1625, 1772 & 5025 13 circuit and larger are being made obsolete due to low demad for these parts.		
000000			
Series image - reference only Part Numbers Affected	Please refer to CustomerPartList.csv attached to	e-mail message.	
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	Not Applicable		
Internal Molex Qualification Date (Planned Date Information Available)			
Sample Availability Date (Changed Part)			
Date of Implementation	August 04, 2016		
Method of Identifying Change	Not Applicable		
Recommended Replacement Parts	No replacement parts		
Last Time Buy Date for Obsolete Parts	May 31, 2016		
Last Time Ship Date for Obsolete Parts	June 13, 2016		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com