

Global Change Notification (GCN)

Product Family	.093" Pin and Socket Plug Housing	10710374		
		GCN Number		
Series	1292	September 01, 2015		
		Date Issued		
Reason For Change	Obsolescence			
Change Description	This letter is being sent to announce that part 3092091 is being made obsolete because the tooling is worn beyond repair and low customer demand.			
Series image - reference onl	ace only			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-n	nail message.		
Reason For Short Notice Exception				
Assessment Of Change (How Product Will Be Qualified & Validated)	Not Applicable			
Internal Molex Qualification Date (Planned Date Information Available)				
Sample Availability Date (Changed Part)				
Date of Implementation	September 01, 2016			
Method of Identifying Change	Not Applicable			
Recommended Replacement Parts	Free hanging part 3092092 is available as a possible replacement.			
Last Time Buy Date for Obsolete Parts	February 12, 2016			
Last Time Ship Date for Obsolete Parts	February 12, 2016			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com