

Product Change Notification (PCN)

PCN Number

501881

Date Issued

March 17, 2017

Reason for Change

Change to Product

Change Type Description

This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.

Reason for Short Notice

Special Request

Assessment of Change

Test report/Specification Test Report

Internal Molex Qualification Date

December 01, 2016

Sample Availability Date (Changed Part)

December 01, 2016

Planned Implementation Date

November 01, 2017

Method of Identifying Change

Lot information on label

Before Change



After Change

Overview

- Plating process will be changed with the project transfer from LNK to CD, The new plating will have gold flash in the initial contact area and 50u gold in the contact resting area vs. the old process with nickel plating in initial contact area and 50u gold in the contact resting area, The only impact is the slight visual difference to the terminal plating, otherwise fit and function are not affected.
- Product Impact
 - no impact to fit and function
- Part Number Impact
- see attached impacted parts list

 PPAP and samples available upon reques



molex



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:501881" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com Molex Part #

......