

## **Product Change Notification (PCN)**

PCN Number 502140 Date Issued March 21, 2017

Reason for Change | Supplier Change

Change Type Description This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in

this notice. There will be no negative impact to product

performance as a result of this change.

Reason for Short Notice | Force Majeure

Assessment of Change | Product will be fully qualified before it is shipped. Qualification

reports are available upon request.

Internal Molex Qualification Date | April 28, 2017

Sample Availability Date (Changed Part) April 28, 2017

Planned Implementation Date | April 28, 2017

Method of Identifying Change | Product made after planned implementation date can contain the change

### Before Change

Molex will change manufacturing suppliers for 501783/501784 series.
(0.5 FFC TO BOARD CONN PLUG JACKET / COVER)

- This is due to a business termination with the current supplier.
- Transferred Products: 501783-3009/501783-4009, 501784-3008/ 501784-3009/501784-4009
- Molding dies will be transferred to the new supplier.

#### After Change

Production in the new supplier is going to start around 2017/4/28. (This date will be changeable by each product, or due to transfer arrangements)

There will be no change on Products' Fit, Form, Function, or Appearance.



## **Product Change Notification (PCN)**

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:502140" in the e-mail Subject line for faster response.

# RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com Molex Part # 5017833009 5017843008