

Product Change Notification (PCN)

PCN Number	509550	Date Issued	December 11, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform y part(s) identified in this form, function or appea change to the specifica of the possible difference	Notice. The chang rance of the parts, tion. The pictures b	e may affect the fit,
Reason for Short Notice	Corrective Actions		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	October 23, 2020		
Sample Availability Date (Changed Part)	October 23, 2020		
Planned Implementation Date	January 15, 2021		
Method of Identifying Change	No special marking on	the product or pac	kaging
Defere Change	Attor C	h a a a a	

Before Change

document correction : top tape peeling strength

- Correct unit Conversion \pm 10.2 \sim 132.5 gf = 0.1 \sim 1.3N





BEFORE Drawing No. 5031540000-SD PSD 000, Rev.A AFTER Drawing No. 5031540000-SD PSD 000, Rev.B

After Change

Summary

- the drawing for 503154series is going to be corrected. 0.3 N is not matched to 132.5 gf, and the specification 10.2~132.5 gf is same as JIS and EIA standard.
- Product Impact
 - No impact to Fit, Form or Function.
 There is no change as product itself.
- Part Number Impact
 503154series

molex[®]

Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509550**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

PCN #	Molex Part #	
509550	5031540890	
509550	5031541090	
509550	5031541490	
509550	5031541690	
509550	5031541890	
509550	5031542090	
509550	5031542290	
509550	5031542490	
509550	5031542690	
509550	5031542890	
509550	5031543290	
509550	5031543490	

Part numbers affected:

503154-1290 503154-2890