

## Product End-of-Life Notification

# MT5600SMI Series Only SocketModem<sup>®</sup> Embedded Analog Modems



Date: December 19, 2017

### I. Summary

Due to a critical component end-of-life, the status of the MT5600SMI family of embedded analog SocketModems are changing status from **Near-End-of-Life (NEOL) to End-of-Life (EOL)** effective immediately.

Orders previously accepted via a Non-Cancellable, Non-Returnable (NCNR) purchase order will be fulfilled and shipped on the agreed upon dates.

#### Contents:

- [I. Summary](#)
- [II. Part Numbers Impacted and Suggested Replacement](#)
- [III. Key Dates](#)
- [IV. Warranty and Support](#)
- [V. Suggested Action Plan](#)
- [VI. Additional Information](#)

### II. Part Numbers Impacted and Suggested Replacement

EOL Ordering Part Numbers	UPC	Recommended Replacement Ordering Part Numbers	UPC
MT5600SMI-32.R2	789407337031	MT5692SMI-34.R1	789407351952
MT5600SMI-32.R2-SP	789407337079	MT5692SMI-34.R1-SP	789407351969
MT5600SMI-L-32.R2	789407337055	MT5692SMI-L-34.R1	789407351976
MT5600SMI-L-32.R2-SP	789407337048	MT5692SMI-L-34.R1-SP	789407351983
MT5600SMI-P-32.R2	789407337253	MT5692SMI-P-34.R1	789407351990
MT5600SMI-P-32.R2-SP	789407337093	MT5692SMI-P-34.R1-SP	789407352003
MT5600SMI-34.R2	789407337116	MT5692SMI-34.R1	789407351952
MT5600SMI-34.R2-SP	789407337109	MT5692SMI-34.R1-SP	789407351969
MT5600SMI-L-34.R2	789407337130	MT5692SMI-L-34.R1	789407351976
MT5600SMI-L-34.R2-SP	789407337123	MT5692SMI-L-34.R1-SP	789407351983
MT5600SMI-P-34.R2	789407336836	MT5692SMI-P-34.R1	789407351990
MT5600SMI-P-34.R2-SP	789407336829	MT5692SMI-P-34.R1-SP	789407352003
MT5600SMI-P-L-34.R2	789407336850	MT5692SMI-P-L-34.R1	789407352010
MT5600SMI-P-L-34.R2-SP	789407336843	MT5692SMI-P-L-34.R1-SP	789407352027
MT5600SMI-X-L-34.R2	789407336812	MT5692SMI-X-L-92.R1	789407352157
MT5600SMI-X-L-34.R2-SP	789407336805	MT5692SMI-X-L-92.R1-SP	789407352164
MT5600SMI-92.R2	789407337147	MT5692SMI-92.R1	789407352058

EOL Ordering Part Numbers	UPC	Recommended Replacement Ordering Part Numbers	UPC
MT5600SMI-92.R2-SP	789407338120	MT5692SMI-92.R1-SP	789407352065
MT5600SMI-L-92.R2	789407337161	MT5692SMI-L-92.R1	789407352072
MT5600SMI-L-92.R2-SP	789407337154	MT5692SMI-L-92.R1-SP	789407352089
MT5600SMI-P-92.R2	789407337215	MT5692SMI-P-92.R1	789407352096
MT5600SMI-P-92.R2-SP	789407337208	MT5692SMI-P-92.R1-SP	789407352102
MT5600SMI-P-L-92.R2	789407337239	MT5692SMI-P-L-92.R1	789407352119
MT5600SMI-P-L-92.R2-SP	789407337222	MT5692SMI-P-L-92.R1-SP	789407352126
MT5600SMI-X-L-92.R2	789407337185	MT5692SMI-X-L-92.R1	789407352157
MT5600SMI-X-L-92.R2-SP	789407337178	MT5692SMI-X-L-92.R1-SP	789407352164

### III. Key Dates

**Near-End-of-Life (NEOL) Date:** June 27, 2017

**Last Time Buy Date:** December 27, 2017 or while supplies last

**Last Ship Date:** March 27, 2018 or while supplies last

**End-of-Life (EOL) Date:** December 19, 2017

### IV. Warranty and Support

MultiTech will provide technical support and repair or exchange of the products listed in this announcement through the warranty period of the installed device. However, no firmware/software updates or maintenance releases will take place post NEOL date.

### V. Suggested Action Plan:

We recommend the following actions be taken:

- Forward this announcement to others within your organization who are actively involved in the sale or support of the devices listed in this announcement.
- Note that the current MT5600SMI-xx models are no longer available.
- Work with your MultiTech sales representative to discuss replacement options for these EOL models.

### VI. Additional Information

If you have any questions or require additional information on this Product End-of-Life Notification, please contact your MultiTech sales representative:

#### World Headquarters – U.S.

+(763) 785-3500 | [sales@multitech.com](mailto:sales@multitech.com)

#### EMEA Headquarters – UK:

+(44) 118 959 7774 | [sales@multitech.co.uk](mailto:sales@multitech.co.uk)