

## PRODUCT OBSOLESCENCE NOTICE

December 22, 2009

Dear Customer,

Murata Power Solutions (MPS) hereby gives official notification that the following product(s) you may have purchased from us are becoming obsolete with immediate effect:

Product Part Number	Recommended Alternative
NPX20S24018DC	UWR-1.8/6000-D24ACT-C
NPX20S24018MC	UWR-1.8/6000-D24ACT-C
NPX20S24018PMC	UWR-1.8/6000-D24ACT-C
NPX20S24025DC	UWR-2.5/6000-D24ACT-C
NPX20S24025MC	UWR-2.5/6000-D24ACT-C
NPX20S24025PMC	UWR-2.5/6000-D24ACT-C
NPX20S24033DC	NPH25S2403EiC
NPX20S24033MC	NPH25S2403EiC
NPX20S24033PMC	NPH25S2403EiC
NPX20S48018DC	UWR-1.8/6000-D48ACT-C
NPX20S48018MC	UWR-1.8/6000-D48ACT-C
NPX20S48018PMC	UWR-1.8/6000-D48ACT-C
NPX20S48025DC	UWR-2.5/6000-D48ACT-C
NPX20S48025MC	UWR-2.5/6000-D48ACT-C
NPX20S48025PMC	UWR-2.5/6000-D48ACT-C
NPX20S48033DC	NPH25S4803EiC
NPX20S48033MC	NPH25S4803EiC
NPX20S48033PMC	NPH25S4803EiC

Via this notice we are offering our customers the opportunity for a last time or lifetime buy (LTB) and we will accept orders until 31<sup>st</sup> March 2010. Please note that this LTB may be subject to a minimum order quantity. Multiple releases will be accepted with a constraint that no releases may be scheduled past a ship date of 31<sup>st</sup> August 2010. Once placed, LTB orders cannot be cancelled, rescheduled, or returned for non-quality reasons. Quality issues need to be identified and communicated within 30 days of shipment.

Should you have any questions or concerns please contact your local MPS Representative, Distributor, or Regional Sales Manager at <a href="http://www.murata-ps.com/offices.html">http://www.murata-ps.com/offices.html</a>.