

November 13, 2015

Dear Valued Customer:

NMB Technologies, Inc had made a decision to stop production of many models and thus we issued a corresponding EOL notices. In addition we also notified our customers about several models that we wanted to EOL and to start converting to newer models.

After much discussion and overwhelming customer demand, we have convinced our factory to postpone each Phase of the initiatives until further notice.

This means the legacy series/part numbers targeted for EOL will still be available and as a reminder we encourage all new designs to focus on promoting the new P/N. Please refer to the attached lists for the Legacy Series.

As always, please let us know if you have any questions. Thanks for your understanding and cooperation!

Sincerely, NMB Techologies, Inc

2015 EOL Master Table - Phase I Legacy Series 1004KL 1204KL 1404KL 1606KL 2004KL 2106KL 2404KL 2806KL 2810KL 3106KL 3112KL 3122FT 3615FB 3615KL 3615RL 4712KL 5015KL **BM4515** BM5115 BM5125 **BM6015 BM6025 BG0702 BG0801 BG1002**

BT1002 BM4212

2015 EOL Master Table - Phase II

Legacy Series	New Replacement Series
1604KL	New Part # 04010KA Series recommended replacement.
1608KL	New Part # 04020VA Series recommended replacement.
1611FT	New Part # 04028DA Series recommended replacement.
1611RL	New Part # 04028DA Series recommended replacement.
2406KL	New Part # 06015KA Series recommended replacement.
2408NL	New Part # 06020SA series recommended replacement.
2410ML	New Part # 06025SA series recommended replacement.
2415KL	New Part # 06038DA series recommended replacement.
3108NL	New Part # 08020KA series recommended replacement.
3110KL	New Part # 08025SA series recommended replacement.
3110PS	New Part # 08025MB series recommended replacement.
3115FT	New Part # 08038DA series recommended replacement.
3115RL	New Part # 08038DA series recommended replacement.
3610KL	New Part # 09225SA series recommended replacement.
3612KL	New Part # 09232VA series recommended replacement.
4710KL	New Part # 11925SA series recommended replacement.
4715PS	New Part # 11938MB series recommended replacement.
4715SL	New Part # 12038VA series recommended replacement.
5910PL	New Part # 15025VA series recommended replacement.
5920PL	New Part # 15050VA series recommended replacement.
6820PL	New Part # 17250VA series recommended replacement.
BM6920	New Part # 06920GS series recommended replacement.

2015 EOL Master Table - Phase IIa

<u>Legacy</u> Series	New Part Number Series	Comments
1604KL	04010KA	Strictly P/N Change. Same form, fit and function as 1604KL Series model - use new Part Numbering System.
1608VL	04020VA	Strictly P/N Change. Same form, fit and function as 1608VL Series model - use new Part Numbering System.
2406VL	06015VA	Strictly P/N Change. Same form, fit and function as 2406VL Series model - use new Part Numbering System.
2408SB	06020SA	Strictly P/N Change . Same form, fit and function as 2408SB Series model - use new Part Numbering System.
2410SB	06025SA	Strictly P/N Change . Same form, fit and function as 2410SB Series model - use new Part Numbering System.
3108SB	08020SA	Strictly P/N Change . Same form, fit and function as 3108SB Series model - use new Part Numbering System.
3110SB	08025SA	Strictly P/N Change . Same form, fit and function as 3110SB Series model - use new Part Numbering System.
3610SB	09225SA	Strictly P/N Change . Same form, fit and function as 3610SB Series model - use new Part Numbering System.
3610VL	09225VA	Strictly P/N Change . Same form, fit and function as 3610VL Series model - use new Part Numbering System.
4715KL	11938KA	Strictly P/N Change . Same form, fit and function as 4715KL Series model - use new Part Numbering System.
4715VL	12038VA	Strictly P/N Change . Same form, fit and function as 4715VL Series model - use new Part Numbering System.
BG0903	09533GA	Strictly P/N Change . Same form, fit and function as BG0903 Series model - use new Part Numbering System.
BG1203	12032GA	Strictly P/N Change . Same form, fit and function as BG1203 Series model - use new Part Numbering System.