

XF2R FPC Connector Discontinued, end of FY2008

Due to reduction in overall global demand, Omron is discontinuing the XF2R FPC connector. Effective March 30, 2009, the XF2R connectors will no longer be produced. Omron is not offering or recommending a replacement to this part.

The Last Order Date for the XF2R will be January 31, 2009.

Discontinued product	Recommended Replacement
XF2R-**15-4A	No replacement

Parts number of Discontinuation

Item Code	Product Description
XF2R0002E	XF2R-0615-4A
XF2R0007F	XF2R-0915-4A
XF2R0011D	XF2R-1815-4A
XF2R0012B	XF2R-2415-4A
XF2R0003C	XF2R-3415-4A
XF2R0005M	XF2R-4015-4A

Omron strongly recommends placing last time buy orders right away. Final orders will be accepted *<u>no later than</u>* January 31, 2009.

Please contact Product Manager, <u>Tomoko Abe</u> with further questions.