

PRODUCT CHANGE NOTIFICATION

COMPUTER PRINTABLES		20220715-1				
ID AND SAFFTY						
✓ NA	✓ EMEA	✓ LATAM	✓ AP			
_						
OTHER						
(Required)						
The WrapID Tooling will be discontinued in November of 2022. Effective November 1, 2022, the WrapID tooling listed below will be changed to a status of Use Up. •PLA-100, PLA-100/E, PLA-H100, PLA-R, PLA-R/E, PLA-S Any inventory remaining after November 1, 2022 will be sold only while supplies last. The labels and consumables for use with the WrapID tooling will not be discontinued. We plan to continue providing repair and technical support through November 1, 2024. We also plan to continue selling the WrapID labels and associated consumables (ribbons, tethers, spools) through November 1, 2025.						
	IT PART NUMBER	RS: (where appli	cable)			
	✓ NA ✓ DISCONTINUATION ☐ OTHER (Required) discontinued in Novemb Jp. 1100, PLA-R, PLA-R/E, PL ter November 1, 2022 w discontinued. We plan to the WrapID labels and Dlicable)	ID AND SAFI NA EMEA DISCONTINUATION OTHER (Required) discontinued in November of 2022. Effection Jp. 1100, PLA-R, PLA-R/E, PLA-S There is november 1, 2022 will be sold only which is sold in the Wrapid labels and associated consumption of the Wrapid labels and associated consumptions. Discontinued. We plan to continue providing the Wrapid labels and associated consumptions.	ID AND SAFETY NA	ID AND SAFETY 15-Jul-22 NA EMEA LATAM AP DISCONTINUATION OTHER (Required) discontinued in November of 2022. Effective November 1, 2022, the Wrapl Up. 1100, PLA-R, PLA-R/E, PLA-S ter November 1, 2022 will be sold only while supplies last. The labels and colliscontinued. We plan to continue providing repair and technical support the the WraplD labels and associated consumables (ribbons, tethers, spools) to		

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

Reference Page 2 / Linked PDF

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	11	1

^{*}Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED		
PART		Discontinuation
NUMBER(s)	Compatibility Type	Date
PLA-100	No Replacement	1-Nov-22
PLA-100/E	No Replacement	1-Nov-22
PLA-H100	No Replacement	1-Nov-22
PLA-R	No Replacement	1-Nov-22
PLA-R/E	No Replacement	1-Nov-22
PLA-S	No Replacement	1-Nov-22