



Product Change Notification

PCN#: COPPER CABLE- 2018-04-02-1 Issue Date: 16Apr2018

Impacted Regions: NA EMEA LATAM AP

Reason for Change: Discontinuation Other

DESCRIPTION OF CHANGE: *(Not required for discontinuation)*

The Cat 6A UTP series of cables with a plenum (CMP) flammability rating (PUP6AM04**-UG, PUP6XC04**-UG and PUP6ASD04**-UG) are being discontinued. They have been replaced by new cables – Vari-Matrix (PUP6AV04**-G) and TX6A Standard Compliant (PUP6AS04**-G). These new cables are the smallest Cat 6A 100m cables on the market today.

PHOTOS/DRAWING *(where applicable)*

IMPACTED PART NUMBERS AND REPLACEMENT (where applicable) PART NUMBERS:

[Reference page 2/linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

Schedule for Change	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2018	04	02
Old product discontinuation date*	2018	08	01

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.

CUSTOMER SERVICE CONTACTS:

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CustomerService@panduit.com	CHINA: 800-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed Line) 000 800 6500369 (Mobile) IND-customer_service@panduit.com	INDONESIA: 001 803 65 7571 SGP-customer_service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA: 1800 801435 SGP-customer_service@panduit.com	SINGAPORE: 1-800-7263848 SGP-CUSTOMER_SERVICE@panduit.com	
	TAIWAN: 0080 165 1487 SGP-CUSTOMER_SERVICE@panduit.com	THAILAND: 001-800-65-6385 SGP-customer_service@panduit.com		
LATIN AMERICA	BRAZIL: 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000, X80520 01 800 360 86 00 (Toll Free) mex-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com	
	NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA Phone: +44 208 6017219 EMEA-CustomerServices@panduit.com	

To add a contact or to unsubscribe, please send an e-mail to PCN@panduit.com



IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
PUP6AM04BU-UG	PUP6AV04BU-G
PUP6AM04WH-UG	PUP6AV04WH-G
PUP6AM04IG-UG	PUP6AV04IG-G
PUP6AM04YL-UG	PUP6AV04YL-G
PUP6AM04GR-UG	PUP6AV04GR-G
PUP6AM04RD-UG	PUP6AV04RD-G
PUP6AM04VL-UG	PUP6AV04VL-G
PUP6AM04OR-UG	PUP6AV04OR-G
PUP6AM04BL-UG	PUP6AV04BL-UG
PUP6XC04BU-UG	PUP6AS04BU-G
PUP6XC04WH-UG	PUP6AS04WH-G
PUP6XC04IG-UG	PUP6AS04IG-G
PUP6XC04YL-UG	PUP6AS04YL-G
PUP6XC04GR-UG	PUP6AS04GR-G
PUP6XC04RD-UG	PUP6AS04RD-G
PUP6XC04VL-UG	PUP6AS04VL-G
PUP6XC04OR-UG	PUP6AS04OR-G
PUP6XC04BL-UG	PUP6AS04BL-UG
PUP6ASD04BU-UG	PUP6AV04BU-G or PUP6AS04BU-G
PUP6ASD04WH-UG	PUP6AV04WH-G or PUP6AS04WH-G
PUP6ASD04IG-UG	PUP6AV04IG-G or PUP6AS04IG-G
PUP6ASD04YL-UG	PUP6AV04YL-G or PUP6AS04YL-G
PUP6ASD04GR-UG	PUP6AV04GR-G or PUP6AS04GR-G
PUP6ASD04RD-UG	PUP6AV04RD-G or PUP6AS04RD-G
PUP6ASD04VL-UG	PUP6AV04VL-G or PUP6AS04VL-G
PUP6ASD04OR-UG	PUP6AV04OR-G or PUP6AS04OR-G
PUP6ASD04BL-UG	PUP6AV04BL-UG or PUP6AS04BL-UG