

# PRODUCT CHANGE NOTIFICATION

Product Category SAFETY PTD 20211206-1

Product Group ID AND SAFETY

ISSUE DATE: 6-Dec-21

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Panduit is obsoleting the VeriSafe retrofit kits to provide a simpler and more streamlined offering of the VeriSafe product line. The VeriSafe retrofit kits can be directly replaced by ordering an AVT and appropriate insulation piercing connector kit.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	1	31
Old product discontinuation date*	2022	1	31

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2
VS-AVT-RKP1	Complex	VS-AVT-C08-L10	VS-CKP14-6
VS-AVT-RKP2	Complex	VS-AVT-C08-L10	VS-CKP4-000
VS-AVT-RBOX	No Replacement		