

PRODUCT CHANGE NOTIFICATION

Product Category _	POWER AND CONNECTIVITY	20200310-1			
Product Group	INTELLIGENT INFRASTRUCTURE				
ISSUE DATE:	3	/10/2020			
IMPACTED REGIONS:	N. America				
REASON FOR CHANGE: (Offer optimization				
DESCRIPTION OF CHANGE: (F	Required)				
We are removing the single pack option from the power cord offer. We recommend the customer buy the 10 packs.					
Photos/Drawing (where appli	cable)				
IMPACTED PART NUMBERS	S AND REPLACEMENT PART NUMBERS: (where applicable)				
Reference Page 2 / Linked	PDF				

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

	Year	Month	Day
SCHEDULE FOR CHANGE	(YYYY)	(MM)	(DD)
New product sample availability date	2020	3	10
Old product discontinuation date*	2020	7	31

^{*}Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Туре	Replacement Part 1
LPCA01	Direct Replacement	LPCA01X
LPCA02	Direct Replacement	LPCA02X
LPCA03	Direct Replacement	LPCA03X
LPCA04	Direct Replacement	LPCA04X
LPCA05	Direct Replacement	LPCA05X
LPCA06	Direct Replacement	LPCA06X
LPCA07	Direct Replacement	LPCA07X
LPCA08	Direct Replacement	LPCA08X
LPCA09	Direct Replacement	LPCA09X
LPCA10	Direct Replacement	LPCA10X
LPCA11	Direct Replacement	LPCA11X
LPCA12	Direct Replacement	LPCA12X
LPCA13	Direct Replacement	LPCA13X
LPCA14	Direct Replacement	LPCA14X
LPCA15	Direct Replacement	LPCA15X
LPCA16	Direct Replacement	LPCA15X
LPCA17	Direct Replacement	LPCA16X
LPCA18	·	
	Direct Replacement	LPCA18X
LPCA19	Direct Replacement	LPCA19X
LPCA20	Direct Replacement	LPCA20X
LPCA21	Direct Replacement	LPCA21X
LPCA22	Direct Replacement	LPCA22X
LPCA23	Direct Replacement	LPCA23X
LPCA24	Direct Replacement	LPCA24X
LPCA25	Direct Replacement	LPCA25X
LPCB01	Direct Replacement	LPCB01X
LPCB02	Direct Replacement	LPCB02X
LPCB03	Direct Replacement	LPCB03X
LPCB04	Direct Replacement	LPCB04X
LPCB05	Direct Replacement	LPCB05X
LPCB06	Direct Replacement	LPCB06X
LPCB07	Direct Replacement	LPCB07X
LPCB08	Direct Replacement	LPCB08X
LPCB09	Direct Replacement	LPCB09X
LPCB10	Direct Replacement	LPCB10X
LPCB11	Direct Replacement	LPCB11X
LPCB12	Direct Replacement	LPCB12X
LPCB13	Direct Replacement	LPCB13X
LPCB14	Direct Replacement	LPCB14X
LPCB15	Direct Replacement	LPCB15X
LPCB16	Direct Replacement	LPCB16X
LPCB17	Direct Replacement	LPCB17X
LPCB18	Direct Replacement	LPCB18X
LPCB19	Direct Replacement	LPCB19X
LPCB20	Direct Replacement	LPCB20X
LPCB21	Direct Replacement	LPCB21X

	<u> </u>	1
LPCB22	Direct Replacement	LPCB22X
LPCB23	Direct Replacement	LPCB23X
LPCB24	Direct Replacement	LPCB24X
LPCB25	Direct Replacement	LPCB25X
NPCA01	Direct Replacement	NPCA01X
NPCA02	Direct Replacement	NPCA02X
NPCA03	Direct Replacement	NPCA03X
NPCA04	Direct Replacement	NPCA04X
NPCA05	Direct Replacement	NPCA05X
NPCA06	Direct Replacement	NPCA06X
NPCA07	Direct Replacement	NPCA07X
NPCA08	Direct Replacement	NPCA08X
NPCA09	Direct Replacement	NPCA09X
NPCA10	Direct Replacement	NPCA10X
NPCA11	Direct Replacement	NPCA11X
NPCA12	Direct Replacement	NPCA12X
NPCA13	Direct Replacement	NPCA13X
NPCA14	Direct Replacement	NPCA14X
NPCA15	Direct Replacement	NPCA15X
NPCA16	Direct Replacement	NPCA16X
NPCA17	Direct Replacement	NPCA17X
NPCA18	Direct Replacement	NPCA18X
NPCA19	Direct Replacement	NPCA19X
NPCA20	Direct Replacement	NPCA20X
NPCA21	Direct Replacement	NPCA21X
NPCA22	Direct Replacement	NPCA22X
NPCA23	Direct Replacement	NPCA23X
NPCA24	Direct Replacement	NPCA24X
NPCA25	Direct Replacement	NPCA25X
NPCB01	Direct Replacement	NPCB01X
NPCB02	Direct Replacement	NPCB02X
NPCB03	Direct Replacement	NPCB03X
NPCB04	Direct Replacement	NPCB04X
NPCB05	Direct Replacement	NPCB05X
NPCB06	<u> </u>	
	Direct Replacement	NPCB06X
NPCB07	Direct Replacement	NPCB07X
NPCB08	Direct Replacement	NPCB08X
NPCB09	Direct Replacement	NPCB09X
NPCB10	Direct Replacement	NPCB10X
NPCB11	Direct Replacement	NPCB11X
NPCB12	Direct Replacement	NPCB12X
NPCB13	Direct Replacement	NPCB13X
NPCB14	Direct Replacement	NPCB14X
NPCB15	IDiract Danlacamant	NPCB15X
NPCB16	Direct Replacement	
	Direct Replacement	NPCB16X
NPCB17 NPCB18	·	

NPCB19	Direct Replacement	NPCB19X
NPCB20	Direct Replacement	NPCB20X
NPCB21	Direct Replacement	NPCB21X
NPCB22	Direct Replacement	NPCB22X
NPCB23	Direct Replacement	NPCB23X
NPCB24	Direct Replacement	NPCB24X
NPCB25	Direct Replacement	NPCB25X