

Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #:	DC-14-07	Last Buy Deadline	for Submission of Order:	7-Feb-2015			
Issue Date:	7-Aug-2014	Last Eligible	e Ship Date:	7-Aug-2015			
Contact: Title: Phone #: E-mail:	Younes Fada Marketing Manager +33231785314 Younes.Fada@idt.com						
(List Replacem	S) AFFECTED: nent Part #(s), if any) s as listed in Attachment I will be discontinued.	ATTACHM	ŒNT ■ Yes [□ No			
☐ Replace sle ☐ Obsolete F ☐ Obsolete A	OR DISCONTINUANCE: ower speed with faster speed offerings Fab Technology / Process Assembly Technology / Process Package / Material Market	■ Other:	End of manufacturing agree	ement with NXP.			
CUSTOMER NOTIFICATION: As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information. Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing. If you have any questions, please feel free to contact your local IDT distributor or sales representative.							
Customer:		E-Mail Addre	ss:				
Name/Date:		Phon	e#:				
Title:		Fa	x#:				
CUSTOMER	R COMMENTS:						
IDT ACKNO	OWLEDGEMENT:						
Received By:		Date:					

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
ADC0808S125-DB	None	None	N/A	HSC
ADC0808S125HW-C1	None	None	N/A	HSC
ADC0808S125HW-C18	None	None	N/A	HSC
ADC0808S250-DB	None	None	N/A	HSC
ADC0808S250HW-C1	None	None	N/A	HSC
ADC0808S250HW-C18	None	None	N/A	HSC
ADC1112D125F1-DB	None	None	N/A	HSC
ADC1112D125F2-DB	None	None	N/A	HSC
ADC1112D125HN-C1	None	None	N/A	HSC
ADC1112D125HN-C18	None	None	N/A	HSC
ADC1410S125F1-DB	None	None	N/A	HSC
ADC1410S125F2-DB	None	None	N/A	HSC
ADC1410S125HN-C1	None	None	N/A	HSC
ADC1410S125HN-C18	None	None	N/A	HSC
ADC1412D065F1-DB	None	None	N/A	HSC
ADC1412D065F2-DB	None	None	N/A	HSC
ADC1412D00512-DB ADC1412D065HN-C1	None	None	N/A	HSC
ADC1412D065HN-C18	None	None	N/A	HSC
ADC1412D080F1-DB	None	None	N/A	HSC
ADC1412D080F1-DB	None	None	N/A	HSC
ADC1412D080HN-C1	None	None	N/A	HSC
	None		N/A	HSC
ADC1412D080HN-C18		None		+
ADC1412D105F1-DB	None	None	N/A N/A	HSC
ADC1412D105F2-DB	None	None	'	HSC
ADC1412D105HN-C1	None	None	N/A	HSC
ADC1412D105HN-C18	None	None	N/A	HSC
ADC1412D125F1-DB	None	None	N/A	HSC
ADC1412D125F2-DB	None	None	N/A	HSC
ADC1412D125HN-C1	None	None	N/A	HSC
ADC1412D125HN-C18	None	None	N/A	HSC
ADC1413D065HN-C1	None	None	N/A	HSC
ADC1413D065HN-C18	None	None	N/A	HSC
ADC1413D065W1-DB	None	None	N/A	HSC
ADC1413D065WO-DB	None	None	N/A	HSC
ADC1413D080HN-C1	None	None	N/A	HSC
ADC1413D080HN-C18	None	None	N/A	HSC
ADC1413D080W1-DB	None	None	N/A	HSC
ADC1413D080W2-DB	None	None	N/A	HSC
ADC1413D080WO-DB	None	None	N/A	HSC
ADC1413D105HN-C1	None	None	N/A	HSC
ADC1413D105HN-C18	None	None	N/A	HSC
ADC1413D105W1-DB	None	None	N/A	HSC
ADC1413D105WO-DB	None	None	N/A	HSC
ADC1413D125HN-C1	None	None	N/A	HSC
ADC1413D125HN-C18	None	None	N/A	HSC
ADC1413D125W1-DB	None	None	N/A	HSC
ADC1413D125WO-DB	None	None	N/A	HSC
ADC1413S080HN-C1	None	None	N/A	HSC
ADC1413S080HN-C18	None	None	N/A	HSC
ADC1413S125HN-C1	None	None	N/A	HSC
ADC1413S125HN-C18	None	None	N/A	HSC
ADC1415S125-DB	None	None	N/A	HSC
ADC1415S125F1-DB	None	None	N/A	HSC
ADC1415S125F2-DB	None	None	N/A	HSC
ADC1415S125HN-C1	None	None	N/A	HSC
				HSC
ADC1415S125HN-C18	None	None	N/A	1130
ADC1415S125HN-C18 ADC1610S125F1-DB	None None	None	N/A N/A	HSC

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
ADC1610S125HN-C1	None	None	N/A	HSC
ADC1610S125HN-C18	None	None	N/A	HSC
DAC1201D125HLC1KY	None	None	N/A	HSC
DAC1201D125HLC1KY8	None	None	N/A	HSC
DAC1401D125-DB	None	None	N/A	HSC
DAC1401D125HL-C1	None	None	N/A	HSC
DAC1401D125HL-C18	None	None	N/A	HSC
DAC1405D750-DB	None	None	N/A	HSC
DAC1405D750HW-C1	None	None	N/A	HSC
DAC1405D750HW-C18	None	None	N/A	HSC
TDA9901-DB	None	None	N/A	HSC