

#### 1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.			
SBU PG PUG Type							
02 007 001 0000002311	See list below	Connector	2571 Appliance Inlet C6	n/a			
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)							
List of part numbers affected							
6160.0004 6160.0	0005 616	0.0006	6160.0007	6160.0024			
6160.0045 6160.0	0046 616	0.0047	6160.0056	6160.0057			
6160.0064 6160.0	0068 620	0.4225	3-116-415				

## 2 Type of change

UL upgrade from UL 498 to UL 60320-1.

Marking for UL rating 7A/125V~ updated. Marking for IEC rating 2.5A/250V~ updated.

# 3 Detailed description of change



#### 4 Reason of change

Standards update according to the new UL/CSA 60320-1.

#### 5 Release date

The change takes effect in ww 19/2021 (Date code 2119 or higher on label).

### 6 Impact of change and recommended action

Form Yes Change of rating marking.

Fit No Function No Manufacturing No Label No Packaging No -

#### 7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet 2571	

Product Change Notification			2571 Change of marking					
owner	creation date	release date	released by	change order no	rev	page	D40 050 000	
zeierjo	31.03.2021	31.03.2021	muehlema	2020483	В	1 of 1	D10-052-928	