

#### 1 Products affected

Product hierarchy no. *			y no. *	Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
01	002	042	0000000585	0751.0505 0751.0506	Circuit Protection	CSO Clip	

<sup>\*</sup>SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

## 2 Type of change

Change of material

# 3 Detailed description of change

The material change communicated with PCN D10-061-218 does not affect the silver plated CSO clips with THT technology. Please refer to the part numbers mentioned above.

## 4 Reason of change

Correction of PCN D10-061-218

#### 5 Release date

No change on the mentioned part numbers.

6 Impact of change and recommend	ed	action
----------------------------------	----	--------

$\boxtimes$	Form	No action required
	Fit	
	Function	
	Manufacturing	
	Label	

### 7 Reference Documents

Packaging

Kind of document	Document Title		
Data Sheet	CSO Clip		

Product Change Notification				PCN CSO material change update				
owner	creation date	release date	released by	change order no	rev	page	D40 062 277	
burripa	21.02.2022	22.02.2022	schulejo	2023539	Α	1 of 1	D10-063-377	