

**1 Products affected**

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.	
SBU	PG	PGU	Type				
01	001	025	0000000207	See list below	Circuit Protection	UST 1206	n/a


\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
3413.0326.11	3413.0328.11	3413.0330.11	3413.0331.11	3413.0332.11
3413.0326.22	3413.0328.22	3413.0330.22	3413.0331.22	3413.0332.22
3413.0326.24	3413.0328.24	3413.0330.24	3413.0331.24	3413.0332.24
3413.0326.26	3413.0328.26	3413.0330.26	3413.0331.26	3413.0332.26
3413.0327.11	3413.0328.CI			
3413.0327.22	3413.0328.80			
3413.0327.24	3413.0329.11			
3413.0327.26	3413.0329.22			
3413.0327.80	3413.0329.24			
	3413.0329.26			

**2 Type of change**

- Improved marking readability
- Adjusted layout of conductive path

**3 Detailed description of change**



Letters do not change

**4 Reason of change**

- Improve marking readability with a better contrast of the letter
- Improved layout of conductive path

**5 Release date**

The change will be rolled-out starting week 05/2016 (Date code 1605 or higher on label) and lasts approx. 6 months depending on the variant.

UST 1206					0118.2312	
creation date	created by	release date	released by	notification no.	revision	page
2015-09-24	ruettiha	2015-12-04	ruettiha	-	-	1 of 2

## 6 Impact of change and recommended action

Form	Yes	New product marking, adjusted layout of conductive path
Fit	No	No dimension change
Function	No	No function change
Production Site	No	Production site remains
Product Label	No	No label change
Customer Action	No	Notification only

## 7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet	<a href="#">WEB Link UST 1206</a>

UST 1206					0118.2312	
creation date	created by	release date	released by	notification no.	revision	page
2015-09-24	ruettiha	2015-12-04	ruettiha	-	-	2 of 2