

# SIERRA WIRELESS PRODUCT CHANGE NOTICE

## **OVERVIEW**

DATE ISSUED:	December 10, 2021	TRACKING NUMBER:	4134912
ISSUED BY:	IoT Solutions Product Management		
PRODUCTS AFFECTED:	FX30 LTE-M	FX30 LTE CAT-1 NAM	FX30 LTE CAT-1 EMEA
	FX30S LTE-M	FX30S LTE CAT-1 NAM	
SKUS AFFECTED:	All active SKUs for products affected		
BULLETIN:	Change in Standard Hardware Warranty for FX30 and FX30S		
URGENCY:	Normal		
FOR DISTRIBUTION TO:	Customers using products affected and their partners		

## Summary

Change to standard hardware warranty for FX30 and FX30S.

## Change details

Standard hardware warranty for all FX30 and FX30S products will be changed to 1 year from the Date of Purchase.

For the full warranty terms, please see:

- For customers who buy directly from Sierra Wireless: <u>www.sierrawireless.com/terms-of-sale</u>
- For customers who buy from Sierra Wireless authorized resellers: <u>www.sierrawireless.com/end-user-warranty</u>

Extended warranty can still be purchased for up to 5 years. Please contact Sierra Wireless for more information on extended warranty.

## Timeline

This change will apply to new orders starting on January 1, 2022

## More information

For more information, please contact your Sierra Wireless sales/technical support representative.